



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III3district.htm](http://emnrd.state.nm.us/ocd/District%20III3district.htm)

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test 9-23-10 Operator Enwest - Glorion API #30-0 3923251

Property Name SIC. Apt. 125 Well No. 12 Location: Unit N Section 25 Township 25N Range 4W

Well Status (Shut-In or Producing) Tubing 80 Intermediate NA Casing 125 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES: INTERMEDIATE	CASING	BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes	<u>NA</u>	<u>130</u>	Steady Flow	<u>NA</u>
10 minutes	<u></u>	<u>125</u>	Surges	<u></u>
15 minutes	<u></u>	<u></u>	Down to Nothing	<u></u>
20 minutes	<u></u>	<u></u>	Nothing ☒	<u></u>
25 minutes	<u></u>	<u></u>	Gas	<u></u>
30 minutes	<u></u>	<u></u>	Gas & Water	<u></u>
			Water	<u></u>

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE NA

REMARKS:

By Glorion Vigil

Witness

pumper
(Position)

