



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrds.state.nm.us/ocd/District III/3district.htm](http://emrds.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test 9-23-10 Operator ENERVEST Drilling API #30-0 3924093
Property Name Jicarilla Apache A118 Well No. 24 Location: Unit L Section 25 Township 24N Range 3W
Well Status(Shut-In or Producing) Producing Tubing 52 Intermediate NA Casing 84 Bradenhead 1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	INTERMEDIATE	CASING		
5 minutes	<u>NA</u>	<u>84</u>	Steady Flow	<u>NA</u>
10 minutes	<u>—</u>	<u>84</u>	Surges	<u>—</u>
15 minutes	<u>—</u>	<u>84</u>	Down to Nothing <u>X</u>	<u>—</u>
20 minutes	<u>—</u>	<u>—</u>	Nothing	<u>—</u>
25 minutes	<u>—</u>	<u>—</u>	Gas	<u>—</u>
30 minutes	<u>—</u>	<u>—</u>	Gas & Water	<u>—</u>
			Water	<u>—</u>

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR — FRESH — SALTY — SULFUR — BLACK —

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE NA

REMARKS:

Blew Down in 2 seconds

By Dwain Harrison
Lease Operator
(Position)

Witness —

