



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.d.state.nm.us/ocd/District III3district.htm](http://emnr.d.state.nm.us/ocd/District%20III3district.htm)

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test 10-19-10 Operator Ener Vest API #30-0 39-21895
Property Name Apache 129 Well No. 121 Location: Unit A Section 13 Township 24N Range 4W
Well Status(Shut-In or Producing) Tubing 60 Intermediate NA Casing 60 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	INTERMEDIATE	CASING		
5 minutes	<u>NA</u>	<u>60</u>	Steady Flow	<u>NA</u>
10 minutes	<u></u>	<u>60</u>	Surges	<u></u>
15 minutes	<u></u>	<u></u>	Down to Nothing	<u></u>
20 minutes	<u></u>	<u></u>	Nothing	<u></u>
25 minutes	<u></u>	<u></u>	Gas	<u></u>
30 minutes	<u></u>	<u></u>	Gas & Water	<u></u>
			Water	<u></u>

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE NA

REMARKS:

NO Braden head pressure 0

By Leonard Lucum
Pumpin
(Position)

Witness

