



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III3distr.htm](http://emnr.state.nm.us/ocd/District%20III3distr.htm)

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test 9-28-10 Operator Overwest API #30-0 3923662

Property Name Sic. Co. 126 Well No. 143 Location: Unit 9 Section 2 Township 24N Range 4W

Well Status (Shut-In or Producing) Tubing 110 Intermediate NA Casing 140 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	INTERMEDIATE	CASING		
5 minutes	<u>NA</u>	<u>140</u>	Steady Flow	<u>NA</u>
10 minutes	<u> </u>	<u>↓</u>	Surges	<u> </u>
15 minutes	<u> </u>	<u> </u>	Down to Nothing	<u> </u>
20 minutes	<u> </u>	<u> </u>	Nothing <u>✓</u>	<u> </u>
25 minutes	<u> </u>	<u> </u>	Gas	<u> </u>
30 minutes	<u> </u>	<u> </u>	Gas & Water	<u> </u>
			Water	<u> </u>

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE NA

REMARKS:

By Grover Vigil
pumper
(Position)

Witness

