

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Burlington Resources, a Wholly Owned Subsidiary of ConocoPhillips Company		Contact Kelsi Gurvitz	
Address 3401 E. 30th St., Farmington, NM 87402		Telephone No. 505-599-3403	
Facility Name Lackey A 3R		Facility Type Gas Well API #3004529528	
Surface Owner Federal	Mineral Owner Federal	Lease No. NMSF-077092-C	

LOCATION OF RELEASE

Unit Letter K	Section 11	Township 29N	Range 10W	Feet from the 1730'	North/South Line South	Feet from the 1455'	East/West Line West	County San Juan
-------------------------	----------------------	------------------------	---------------------	-------------------------------	----------------------------------	-------------------------------	-------------------------------	---------------------------

Latitude **36.73819° N** Longitude **107.8578° W**

NATURE OF RELEASE

Type of Release – Produced Water	Volume of Release – 50 BBL	Volume Recovered – 50 BBL
Source of Release: Pit Tank	Date and Hour of Occurrence unknown	Date and Hour of Discovery 5/3/10 3:00 p.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Brandon Powell	
By Whom? Kelsi Gurvitz	Date and Hour – 5/4/10 3:47 p.m. – verbal and follow-up email	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. RCVD MAY 21 '10 OIL CONS. DIV. DIST. 3	
If a Watercourse was Impacted, Describe Fully.*		

Describe Cause of Problem and Remedial Action Taken.* **On May 4, 2010, it was discovered that there was a leak at the pit tank due to corrosion. Upon discovery, the well was shut in and a water truck was called to location.**

Describe Area Affected and Cleanup Action Taken.* **All fluid remained within the berm and approximately 50 BBL was recovered. COPC will assess the soils and remediate, if needed.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Kelsi Gurvitz</i>	OIL CONSERVATION DIVISION	
Printed Name: Kelsi Gurvitz	Approved by District Supervisor: <i>Brandon Powell</i> For: <i>LP</i>	
Title: Environmental Consultant	Approval Date: 9/22/10	Expiration Date:
E-mail Address: kelsi.m.gurvitz@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 5/18/10 Phone: 505-599-3403		

* Attach Additional Sheets If Necessary

11BP1026635520