District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico **Energy Minerals and Natural Resources**

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Revised October 10, 2003

Form C-141

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

1.				ease Notific	eation	and Co	orrective A	ction	ì			
APE	30-0	39-2	1487			<b>OPERA</b>	ГOR		III Initia	al Report	☐ Fin	al Report
Name of Company Benson-Montin-Greer Drilling Corp				- (	Contact Mike Dimond							
Address 4900 College Blvd, Farmington, NM 87402					Telephone No. 505-325-8874							
Facility Nar	ne Jic. 40	03 #1 (I-17)				Facility Typ	e Well Location	on				
Surface Owner				Jicarilla Apache Nation Lease No. Contract 403								
				LOCA	TION	N OF REI	LEASE					
Unit Letter I	Section 17	Township 27N	Range 1W	Feet from the 1900		h/South Line South Feet from the 460 East/West I East			County Rio Arriba		and the control of th	
	•		Lat	titude		Longitud	le					
				NAT	URE	OF RELI	EASE					
Type of Rele	ase Crude	Oil				Volume of Release 2-? Bbls Volume Recovered 0						
Source of Re						Date and Hour of Occurrence ? Date and Hour			Hour of Disco	overy 05/2	21/06	
Was Immedia	ate Notice (		Vac E	l No FZ N-4 P	د - مارس	If YES, To		aata - Af	101/07 NB	400D D	Faurt 05/	10.6
D Wa o	<u> </u>	•		No T Not Re	equired		l by Jicarilla Inspe		0/21/U6 NN	TOCD Denny	roust U5//	
		by Jicarilla It	rspector			Date and Hour 05/26/06 16:00						
Was a Watercourse Reached?  ☐ Yes ☑ No				If YES, Volume Impacting the Watercourse.								
Well was P& notified 05/2 contaminatio Envirotech.	A'd by BM 3/06 that JA n and called See attached	AECO had rou d Benson-Mor d.	6. BMG to stabout creatin-Greer.	thought Jicarilla A ew excavating sm BMG excavated	all leak	of slop oil fro and called Da	om tank caused what to remove tan	hen val nks. Ci	n tanks rem ve broke. I marron Rou	Discovered moustabout took	ore éxtensi one soil sa	ve ample to
				ten.* BMG havin ill be taken and w							ed soil and	
regulations a public health should their or or the enviro	Il operators or the envi- operations h nment. In a	are required to ronment. The lave failed to a	o report ar acceptant adequately OCD accep	e is true and comp nd/or file certain r ce of a C-141 repo v investigate and r otance of a C-141	elease no ort by the emediate	otifications a e NMOCD m e contaminati	nd perform correct arked as "Final R on that pose a thr	ctive act eport" of eat to g	tions for rel does not rel round wate	eases which n ieve the opera r, surface wat	nay endang itor of liab er, human	ger ility health
	MI	1.1		1			OIL CON	SERV	ATION	DIVISIO		
Signature: Will Miller				Approved by District Supervisor: Brondon Paul For: Charlie Persin								
Printed Name	e: Mike D	imond	· · · · · · · · · · · · · · · · · · ·			Approved by	District Supervis	or: 1/2	oudon	VaueW		
Title: Presid	lent			r		Approval Dat	te: 6-8-00	۔	Expiration	Date:		
E-mail Addre	ess: mikedi	mond@bmgd	rilling.con	n		Conditions of	f Approval:			Attached	<u>ا</u>	
	/03/06	. 10)1		ne: 505-325-8874								
Attach Addi	tional She	ets It Necess	ary				n BP0615	939	490			



## EPA METHOD 8015 Modified Nonhalogenated Volatile Organics Total Petroleum Hydrocarbons

Client:	Benson - Montin - Greer	Project #:	99074-005
Sample ID:	Jicarilla 403 #1	Date Reported:	05-25-06
Laboratory Number:	37230	Date Sampled:	05-23-06
Chain of Custody No:	1011	Date Received:	05-24-06
Sample Matrix:	Soil	Date Extracted:	05-25-06
Preservative:	Cool	Date Analyzed:	05-25-06
Condition:	Cool and Intact	Analysis Requested:	8015 TPH

Parameter	Concentration (mg/Kg)	Det. Limit (mg/Kg)
Gasoline Range (C5 - C10)	35.9	0.2
Diesel Range (C10 - C28)	778	0.1
Total Petroleum Hydrocarbons	814	0.2

ND - Parameter not detected at the stated detection limit.

References:

Method 8015B, Nonhalogenated Volatile Organics, Test Methods for Evaluating Solid Waste,

SW-846, USEPA, December 1996.

Comments:

Jicarilla 403 #1 (I-17).

Muster Walters Analyst

Review Nall