

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

☐ Initial Report ☒ Final Report

Name of Company	Lance Oil & Gas, Inc.	Contact	Jo Becksted
Address	P. O. Box 70, Kirtland, NM 87417	Telephone No.	(505) 598-5601 Ext. 58
Facility Name	Salty Dog #2	Facility Type	Salt Water Disposal
		API #	30-045-30812

Surface Owner	BLM	Mineral Owner	BLM	Lease No.	NMSF-079968
---------------	-----	---------------	-----	-----------	-------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	5	29N	14W	1495	South	1477	East	San Juan

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**



Type of Release	Produced Water	Volume of Release	240 bbls	Volume Recovered	240 bbls
Source of Release	Water Tank overflowed	Date and Hour of Occurrence	6/11/06, time unknown	Date and Hour of Discovery	6/12/06 a.m.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Charlie Perrin & Denny Foust of NMOCD, voice mail for Sherry Landon, BLM			
By Whom?	Jo Becksted	Date and Hour 6/13/06 9:00 a.m.			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A			

If a Watercourse was Impacted, Describe Fully.\* N/A

Describe Cause of Problem and Remedial Action Taken.\* The breaker was tripped so the pump was not functioning (vandalism is a possibility) and the digital alarms did not sound. The overflow tanks overflowed, spilled 240 bbls of produced water into the berm. All water was sucked up and injected into the Salty Dog #2 or Salty Dog #3. Impacted soil was scraped up, soil sample taken to iina ba for testing.

Describe Area Affected and Cleanup Action Taken.\* The soil contained within the berm of the Salty Dog #2 was impacted. The soil was scraped up and will be saved and land farmed.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Jo Becksted		Approved by District Supervisor:  For: Charlie Perrin	
Title: Production Tech	Approval Date: 6/13/06	Expiration Date:	
E-mail Address: jbeckste@westernngas.com	Conditions of Approval:	Attached <input type="checkbox"/>	
Date:	Phone: (505) 598-5601 Ext. 5558		

\* Attach Additional Sheets If Necessary

n 680619440485