

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Enterprise Field Services LLC	Contact: Don Fernald
Address: c/o Environmental Dept. P.O. Box 4324 Houston, Texas 77210-4324	Telephone No. 505-599-2124
Facility Name: Gallegos #2 Well Tie	Facility Type: pipeline - gathering

Surface Owner: Navajo Nation	Mineral Owner	Lease No.
------------------------------	---------------	-----------

LOCATION OF RELEASE

Unit NW/4	Section 29	Township 26 N	Range 11 W	Feet from the	North/South Line	Feet from the	East/West Line	County San Juan
--------------	---------------	------------------	---------------	---------------	------------------	---------------	----------------	--------------------

Latitude _____ Longitude _____

NATURE OF RELEASE



Type of Release: natural gas	Volume of Release: 69 mcf	Volume Recovered: 0
Source of Release: Pipeline	Date and Hour of Occurrence before 8/7/10	Date and Hour of Discovery 8/7/10 - 10:15 AM
Was Immediate Notice Given? Notice provided when shallow groundwater impacts verified <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? n/a	RCVD AUG 26 '10 OIL CONS. DIV.
By Whom? n/a	Date and Hour: n/a	DIST. 3
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
Internal pipeline corrosion suspected at causing leak of natural gas (no liquids) from pipeline - approximately 69 mcf of gas loss estimated from line leak.

Describe Area Affected and Cleanup Action Taken.*
N/A - pipeline repaired.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Don Fernald		Approved by District Supervisor:  For: CP	
Title: Environmental Scientist		Approval Date: 9/17/10	Expiration Date:
E-mail Address: dferald@eprod.com		Conditions of Approval:	Attached <input type="checkbox"/>
Date: 8/20/10 Phone: 505-599-2124			

* Attach Additional Sheets If Necessary

nBP1026447406