

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

☐ Initial Report ☒ Final Report

Name of Company	ConocoPhillips Company	Contact	Juanita Farrell
Address	5525 Hwy. 64, Farmington, NM 87401	Telephone No.	505-599-3419
Facility Name	San Juan 29-6 Unit #55	Facility Type	Producing Gas Well
Surface Owner	Fee	Mineral Owner	Fee
		Lease No.	API # 30-039-07613

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	18	T29N	R6W	1650'	South	1550'	West	Rio Arriba

Latitude 36.72321° Longitude 107.50777°

**NATURE OF RELEASE**

Type of Release - <b>Condensate</b>	Volume of Release - <b>30 BBL</b>	Volume Recovered - <b>none</b>
Source of Release: <b>Leak in 100 bbl condensate tank</b>	Date and Hour of Occurrence <b>01/12/06</b>	Date and Hour of Discovery <b>01/12/06 - 1:00 p.m.</b>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <b>Denny Foust - OCD - via email</b>	
By Whom? <b>Juanita Farrell</b>	Date and Hour - <b>01/12/06 - 2:30 p.m. via e-mail</b>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		

Describe Cause of Problem and Remedial Action Taken.\* **A condensate spill of an estimated 30 BBL was discovered on Wednesday afternoon, 01/12/06, by the lease operator. The spill resulted from a leak in 100 bbl condensate tank. The spilled fluids soaked into the soil around base of tank. There was no standing fluid to be recovered.**

Describe Area Affected and Cleanup Action Taken.\* **Well has been shut-in and the remaining condensate in tank has been transferred to tank at the San Juan 29-6 #61A well location. Tank will be repaired. The spill area will be excavated and replaced with clean soil. All stained soil will be taken to the Envirotech landfarm. Unless further information is discovered upon remediation activities, this will be the final report.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Juanita Farrell</i>		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <b>Juanita Farrell</b>		Approved by District Supervisor: <i>Denny Foust for Charlie Perry</i>	
Title: <b>Regulatory Analyst</b>	Approval Date: <b>1/23/06</b>	Expiration Date:	
E-mail Address: <b>juanita.r.farrell@conocophillips.com</b>	Conditions of Approval:	Attached <input type="checkbox"/>	
Date: <b>01/12/06</b>	Phone: <b>505-599-3419</b>		

\* Attach Additional Sheets If Necessary

N DG-F0602335919