District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

JAP! 2004

Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

## Release Notification and Corrective Action

30 039 23231						OPERAT	ror in	18 1. O	☐ Initia	al Report XXX Final Report	
Name of Company NM&O Operating Company						Contact Cindia Stokes Lui					
Address	<u> 15 East</u>	1sa, OK 74		Telephone No. 918-584-3802							
Facility Name Rucker Lake #2 Facility Type SWD											
Surface Owner Larry Hatley Mineral Owner									Lease N	Lease No.	
LOCATION OF RELEASE											
						South Line	Feet from the	East/W	est Line	County	
2	2   24   25N   2W									Rio Arriba	
LatitudeLongitude											
NATURE OF RELEASE											
Type of Release crude oil Volume of Release 15gal aproxolume Recovered 15gal											
Source of Release Valve left open on SWD & truck							Date and Hour of Occurrence 1/7/04te and Hour of Discovery 1/7/04				
Was Immediate Notice Given?  X▼ Yes □ No □ Not Required						If YES, To Whom? 9:30am MST 11:30 MST					
By Whom? Cindi Stokes						Date and Hour 1/7/04 1:30pm CST					
Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse.					
☐ Yes ဩ No											
If a Watercourse was Impacted, Describe Fully.*											
Describe Cause of Problem and Remedial Action Taken.*											
A bobtail water truck unloaded into our disposal tank and left the valve open to run onto the											
ground and spill a 2'x4' area at side of tank. They disconnected hose and drove off with out											
closing their cap, splattering oil from tank to gate, aprox. 3/4 mile. We then picked up the oil by hand and removed from the snow, before the oil touched the dirt.											
Describe Area Affected and Cleanup Action Taken.*											
The area affected was a 2x4' area at side of tank, the road leading from the tank to yellow											
gate and a 12-14" circle at the gate. After picking up the oil by hand, we transferred to our remediation soil area.											
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger											
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability											
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other											
federal, state, or local laws and/or regulations.											
							OIL CON	SERV	ATION	DIVISION	
Signature: (1) (M) (S)						Denn Fant					
Signature.	-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1			Approved by District Supervisor: Confrank Chaves							
Printed Name: Cindi Stokes							To Frank Unavez				
Title: analyst						Approval Date: 1/28/04 Expiration Date:					
E-mail Addı	ess: cynt	hia_xana	du@sbc	global.net		Conditions o	/ f Approval:			Attached	
Date: 1/1	5/04		Phone	918-584-38	302						
* Attach Add		ets If Necess	ary			n DG	F04028	5 19	169		