

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30 039 23880

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: ELM RIDGE EXPLORATION	Contact: Amy Mackey
Address: PO Box 156, Bloomfield, NM 87413	Telephone No. : 505-632-3476 x 201
Facility Name: Arco Leeson #2	Facility Type: Oil Well

Surface Owner: Betty Lou Leeson Trust	Mineral Owner: Betty Lou Leeson Trust	Lease No.: NM44508
---------------------------------------	---------------------------------------	--------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	27	25N	3W	1855'	NORTH	515'	WEST	RIO ARRIBA

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release: Oil Spill	Volume of Release:	Volume Recovered
Source of Release: 2" 90 degree fitting leaking.	Date and Hr of Occur. 11-26-05	Date and Hour of Discovery 11-28-05
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* The leak occurred on approximately 11-26-05. The leak was discovered on 11-28-05. Oil was coming out of the 2" 90 degree fitting on the separator. The oil was temporarily contained by putting dirt over the oil.

Describe Area Affected and Cleanup Action Taken.* Lindrith Backhoe Service steam cleaned the location in all areas that oil was sprayed. We land farmed the contaminated soil on the Leeson location.
--

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Amy Mackey</i>	OIL CONSERVATION DIVISION	
Printed Name: AMY MACKEY	Approved by District Supervisor: <i>Denny Funt</i> for Charlie Parnen	
Title: PRODUCTION TECHNICIAN	Approval Date: 12/21/05	Expiration Date:
E-mail Address: amackey1@elmridge.net	Conditions of Approval: <i>Weed field inspection.</i>	Attached <input type="checkbox"/>
Date: 12-19-05	Phone: 505-632-3476 x 201	

* Attach Additional Sheets If Necessary

n DG F0535 534419