District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action													
		15 2		OPERATOR									
Name of Co Address 20		Contact Donald Brooks Telephone No. (505) 326-9425											
Facility Nan		Facility Type Gas Well (Coalbed Methane)											
Surface Ow		Lease No. SF – 078387 A											
Surface Ow	LOCATION OF RELEASE												
Unit Letter A	Section 28	Township 31N	Range 08W			South Line	Feet from the 1115	East/V East	Vest Line	County San Juan	County San Juan		
LatitudeLongitude													
NATURE OF RELEASE													
Type of Release: Produced Water (Coalbed Methane) Source of Release; Equalize line on produced water tanks.							Volume of Release: 45 barrels Volume Recovered: 44 ba						
Source of Re	iease, Equa	Date and Hour of Occurrence Date and Hour of Discovery 12/8/2005 1:30 PM 12/8/2005 1:30 PM											
Was Immediate Notice Given? ☐ Yes ☐ No ☐ Not Required							If YES, To Whom? Henry Hurtado						
By Whom? Don Brooks							Date and Hour 12/8/2005 3:40 PM						
Was a Watercourse Reached? ☐ Yes ☑ No							If YES, Volume Impacting the Watercourse.						
If a Watercourse was Impacted, Describe Fully.*													
,													
Describe Cause of Problem and Remedial Action Taken.* An equalize line between two produced tanks froze and split. The tanks were in the process of													
Describe Cause of Problem and Remedial Action Taken. An equalize line between two produced tanks froze and split. The tanks were in the process of installation of tank heaters, but they were not completely hooked up. The work is being completed, as well as moving the equalize lines closer to the tanks themselves.													
Describe Area Affected and Cleanup Action Taken.* The 1 barrel of un-recovered water soaked into the ground within secondary containment, and will be left on site.													
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.													
1		OIL CONSERVATION DIVISION											
Signature:	10	1 Januar Fount											
Printed Nam	e: Donald	Approved by District Supervisor: for charlie Perrin											
Title: Field Environmental Coordinator							Approval Date: 1212205 Expiration Date:						
E-mail Address: brooksd2@bp.com							Conditions of Approval:				Attached		
Date: 12/20	0/2005	_	Phone:	326-9425	_A								
Attach Additional Sheets If Necessary DEC 2005 NDGF 05 35 641725 DIST. DIV.													