District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV

## State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

1220 S. St. Fran	cis Dr., Sant	a Fe, NM 8/505	1	Sa	ınta F	e, NM 875	05					side of form	
Release Notification and Corrective Action													
30	045	312	74		OPE	RATOR		Init	ial Report	X	Final Report		
							Contact Heidi Thrasher						
						Telephone No. (505)598-5601 Ext 44							
Facility Name Salty Dog #3R							Facility Type Salt Water Disposal Well						
Surface Owner Mineral Owner							Lease No. NM 97843						
LOCATION OF RELEASE													
						South Line Feet from the East/West Line County							
A	28	30	14	850'		North	770'	F	EL	San Juan			
LatitudeLongitude													
NATURE OF RELEASE													
Type of Release Produced water							Volume of Release Aprox. 20 Volume Recovered Aprox 10 bbls						
C CD I - Dad date - 1' d - 1 - 1 C - d							Bbls Total   flowed into Pit     Date and Hour of Occurrence12-   Date and Hour of Discovery 12					10 10 05	
Source of Release Produced water stored in the tank, spraying from the pump							ox. 12:00 AM		9:30 AM	Hour of Disc	overy	12-18-05	
Was Immediate Notice Given?  X Yes □ No □ Not Required						If YES, To Whom? Denny Foust NMOCD, Mark Kelly BLM							
By Whom? Heidi Thrasher						Date and Hour 12-19-05 11:00 AM							
Was a Watercourse Reached?							If YES, Volume Impacting the Watercourse DEC 2005						
Yes X No									3/2	RECEIV	ED	_ <del>ૢ</del>	
If a Watercourse was Impacted, Describe Fully.*												. 93 33	
N/A													
Describe Cause of Problem and Remedial Action Taken.*The high discharge alarm and High Discharge valve had been shut off. Pump was running. It is believed that this was another incident of sabotage. Pump was shut off. Contractor clean up was initiated.													
Describe Cause of Problem and Remedial Action Taken.*The high discharge alarm and High Discharge valve had been shut off. Pump was running. It is believed that this was another incident of sabotage. Pump was shut off. Contractor clean up was initiated.													
Describe Are	a Affected	and Cleanup	Action Tal	ken.*									
Describe Area Affected and Cleanup Action Taken.*  Water had sprayed outside of building and flowed into pit. Water truck sucked up what was possible. We scraped up contaminated soil. Clean gravel was													
brought in. Area will be reseeded. Area was cleaned up by MAI Contractor.													
-1	10 11 11	· c · · ·			1	.1 1	1 1 1		1.1	ND 44	CD	1- 1	
regulations a	ify that the	information g are required t	o report a	e is true and comp nd/or file certain	nete to release	notifications a	rknowledge and und nerform correct	understan ctive acti	a tnat purs	suant to NMC eases which	mav e	uies and ndanger	
public health	or the envi	ironment. The	acceptan	ce of a C-141 rep	ort by t	he NMOCD m	arked as "Final R	Report" de	oes not rel	ieve the oper	ator o	f liability	
				y investigate and i									
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.													
	M.					****	OIL CON	SERV	ATION	DIVISIO	N		
Signatura	11/			HT'		1 sent Don't							
Approved by District Supervisor:												V .	
Printed Name: Heidi Thrasher							torchartie remy						
Title: Production Clerk							Approval Date: 12/21/05   Expiration Date:						
E-mail Address: hthrashe@westerngas.com							onditions of Approval:  Attached						

12-19-05

Date:

Phone: (505)598-5601-44

<sup>\*</sup> Attach Additional Sheets If Necessary