

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Lance Oil & Gas, Inc.	Contact	Jo Becksted
Address	P. O. Box 70, Kirtland, NM 87417	Telephone No.	(505) 598-5601 Ext. 58
Facility Name	WF FRPC 17 #1	Facility Type	Fruitland Coal Gas well
		API #	30-045-32098

Surface Owner	Fee	Mineral Owner	Fee	Lease No.
---------------	-----	---------------	-----	-----------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	17	29N	14W	1188	North	888	East	San Juan

Latitude _____ Longitude _____

NATURE OF RELEASE


Type of Release	Produced Water	Volume of Release	100 bbls	Volume Recovered	60 bbls
Source of Release	Broken water line.	Date and Hour of Occurrence	12/2/05 approx 3:00 a.m.	Date and Hour of Discovery	12/2/05 @ 3:30 a.m.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mark Kelly of the BLM, Charlie Perrin of NMOCD		
By Whom?	Jo Becksted	Date and Hour	12/2/05 @ 8:45 a.m.		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	N/A		

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken. The new transition line coming from the WF FRPC 17 #1 to our main water line ruptured probably when the earth surrounding this new transition settled, causing stress upon the connection. We will replace this transition with steelclines to prevent this from occurring in the future.

Describe Area Affected and Cleanup Action Taken.* Bar ditch between home of Gary Cole and County Road 6100 and property surrounding and underneath mobile home of Gary Cole.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.



Signature: <i>Jo Becksted</i>		OIL CONSERVATION DIVISION	
Printed Name: Jo Becksted		Approved by District Supervisor: <i>Denny Faust for Charlie Perrin</i>	
Title: Production Tech		Approval Date: 12/22/05 Expiration Date:	
E-mail Address: jbeckste@westerngas.com		Conditions of Approval:	
Date: Phone: (505) 598-5601 Ext. 58		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

h DG F0535656695