

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	ConocoPhillips Company	Contact	Monica D. Olson
Address	5525 Hwy. 64, Farmington, NM 87401	Telephone No.	505-599-3458
Facility Name	San Juan 32-8 Unit #4	Facility Type	Gas Well
		API # 30-045-11414	
Surface Owner	Federal	Mineral Owner	Federal
		Lease No.	SF-079353

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	15	T32N	R8W	1500	South	1650	West	San Juan

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	13 BBL	Volume Recovered	10 BBL
Source of Release	Produced water tank overflowed	Date and Hour of Occurrence	10/8/2003	Date and Hour of Discovery	10/8/2003 - 1400 hr
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Denny Foust - OCD - 10/10/2003 @ 1000 hr - via email Mark Kelly - BLM - 10/10/2003 @ 1000 hr - via email		
By Whom?	Monica D. Olson	Date and Hour	10/10/2003 - 1000 hr		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* The produced water tank overflowed. The trucking contractor said they pulled the contents of the tank Sunday night, but the tank does not produce enough water for it to overflow so soon after. Probable cause is due to contractor failing to pull the contents at their regularly scheduled time. All fluids were contained within the berm on location. 10 BBL of 13 BBL spilled were cleaned up. Remediation of remaining water on location is pending.

Describe Area Affected and Cleanup Action Taken.* All fluids were contained within the berm on location. 10 BBL of 13 BBL spilled were cleaned up. Remediation of remaining water within berm is pending.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	Monica D. Olson	OIL CONSERVATION DIVISION	
Printed Name:	Monica D. Olson	Approved by District Supervisor:	Denny Foust for Frank Chavez
Title:	Safety, Health, Environmental, & Regulatory Technician	Approval Date:	12/22/03
Date:	10/10/2003	Expiration Date:	
Phone:	505-599-3458	Conditions of Approval:	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

n DG F0335653578