

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico,
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised June 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30 045 26840

OPERATOR

☐ Initial Report ☒ Final Report

| | | | |
|-----------------|-----------------------------------|---------------|----------------|
| Name of Company | Burlington Resources | Contact | Ed Hasely |
| Address | P.O. Box 4289 Farmington NM 87499 | Telephone No. | (505) 326-9841 |
| Facility Name | SCOTT 100 | Facility Type | Gas Well |
| Surface Owner | Federal | Mineral Owner | Federal |
| | | Lease No. | NMSF-078604 |

LOCATION OF RELEASE

| | | | | | | | | |
|-------------|---------|----------|-------|---------------|------------------|---------------|----------------|----------|
| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
| H | 29 | 032N | 010W | 1460 | North | 1150 | East | San Juan |

NATURE OF RELEASE

| | | | | | |
|-----------------------------|---|---|----------------------|----------------------------|---------------------|
| Type of Release | Produced Water | Volume of Release | 80 BBLS. | Volume Recovered | 0 BBLS. |
| Source of Release | Water Pipeline | Date and Hour of Occurrence | 1/5/2004 | Date and Hour of Discovery | 1/5/2004 3:00:00 PM |
| Was Immediate Notice Given? | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required | If YES, To Whom? | Denny Foust | | |
| By Whom? | Ed Hasely | Date and Hour | 1/6/2004 11:00:00 AM | | |
| Was a Watercourse Reached? | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | 0 | | |

If a Watercourse was Impacted, Describe Fully.*

NA

Describe Cause of Problem and Remedial Action Taken.*

A hole in a buried Fruitland Coal water pipeline allowed water to surface and run approximately 0.4 miles in the bar ditch along a lease road. A vacuum truck was used to remove all water from the line.

Describe Area Affected and Cleanup Action Taken.*

The water flowed down a bar ditch along a lease road for approximately 0.4 miles. The line has been taken out of service. Once the area thaws and dries out, the soils and vegetation will be evaluated to determine if further action is necessary.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

| | | | |
|--|----------------------------------|----------------|-----------------------------------|
| Signature: | OIL CONSERVATION DIVISION | | |
| Printed Name: | Denny Foust for Frank Chavez | | |
| Title: Environmental Representative | Approved by District Supervisor: | Approval Date: | Expiration Date: |
| E-mail Address: lhasely@br-inc. com or gwurtz@br-inc.com | Conditions of Approval: | 1/08/04 | |
| Date: 1/6/04 Phone: (505) 326-9841 or 9537 | | | Attached <input type="checkbox"/> |

* Attach Additional Sheets If Necessary

NDG-F0400857943