

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised June 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report ☒ Final Report

Name of Company	Burlington Resources	Contact	Ed Hasely
Address	P.O. Box 4289 Farmington NM 87499	Telephone No.	(505) 326-9841
Facility Name	PAGE COM 100	Facility Type	Gas Well
Surface Owner	Fee	Mineral Owner	Fee
		Lease No.	FEE

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	07	032N	010W	1770	South	790	East	San Juan

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	80 BBLS.	Volume Recovered	0 BBLS.
Source of Release	Water Pipeline	Date and Hour of Occurrence	1/5/2004	Date and Hour of Discovery	1/5/2004 2:00:00 PM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Denny Foust		
By Whom?	Ed Hasely	Date and Hour	1/6/2004 11:00:00 AM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	0		

If a Watercourse was Impacted, Describe Fully.\*

NA

Describe Cause of Problem and Remedial Action Taken.\*

A hole in the buried water pipeline allowed Fruitland Coal produced water to flow to surface near the Cedar Hill SWD and travel approximately 400 yards across the frozen ground. A vacuum truck was used to remove all water from the line.

Note Bill Liess (BLM) was notified since the water may have traveled across BLM surface.

Describe Area Affected and Cleanup Action Taken.\*

The water traveled approximately 400 yards across a sagebrush area and a couple lease roads before ending in Cox Canyon wash. The line has been taken out of service. Once the area thaws and dries out, the soils and vegetation will be evaluated to determine further action is necessary.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Ed Hasely</i>	OIL CONSERVATION DIVISION		
Printed Name: Ed Hasely	Approved by District Supervisor: <i>Denny Foust</i> for Frank Chavez		
Title: Environmental Representative	Approval Date: 1/08/04	Expiration Date:	
E-mail Address: lhasely@br-inc. com or gwurtz@br-inc.com	Conditions of Approval: Track impact on soil in the spring	Attached <input type="checkbox"/>	
Date: 1/6/04 Phone: (505) 326-9841 or 9537			

\* Attach Additional Sheets If Necessary

N DGF0400856536