

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	ConocoPhillips	Contact	Monica D. Rodahl
Address	5525 Hwy. 64, Farmington, NM 87401	Telephone No.	505-599-3458
Facility Name	San Juan 29-6 Unit #32	Facility Type	Gas Well
		API #	30-039-07651
Surface Owner	Private - Smith	Mineral Owner	Federal
		Lease No.	NM-012698

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	11	T29N	R6W	1590	South	1090	West	Rio Arriba

NATURE OF RELEASE

Type of Release	Fresh water w/ cement traces	Volume of Release	10 BBL (estimated)	Volume Recovered	none
Source of Release	Water from cleaning a cement pump truck	Date and Hour of Occurrence	1/24/2003 - 1300 hr	Date and Hour of Discovery	1/24/2003 - 1300 hr
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Denny Foust - OCD - 1/24/2003 @ 1600 hr - via email Mark Kelly - BLM - 1/24/2003 @ 1600 hr - via email		
By Whom?	Monica D. Rodahl	Date and Hour	1/24/2003 - 1600 hr		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.* A cement pump truck was cleaning up their unit with fresh water from location after a cement squeeze job. In their attempts to utilize the pit for the disposal of the clean-up water, the water instead ran downhill down the road in a 1-track wide rut for approximately 100 yards.					
Describe Area Affected and Cleanup Action Taken.* Fresh water mixed with traces of cement ran down the lease road in a 1-track wide rut for approximately 100 yards. The roadway was already wet from snowmelt. There are no definite plans of any cleanup as of yet, pending discussion with the landowner.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
Signature:		OIL CONSERVATION DIVISION			
Printed Name:		Approved by District Supervisor: <i>Denny Foust</i> <i>for Frank Chavez</i>			
Title:		Approval Date: <i>03/19/03</i> Expiration Date:			
Date:		Conditions of Approval:			
1/24/2003		Attached <input type="checkbox"/>			
Phone: 505-599-3458					

* Attach Additional Sheets If Necessary

ADGF 0307838553