


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised June 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form



Release Notification and Corrective Action

OPERATOR

30 039 25930

Initial Report ☒ Final Report

Name of Company	Burlington Resources	Contact	Ed Hasely
Address	P.O. Box 4289 Farmington NM 87499	Telephone No.	(505) 326-9841
Facility Name	SAN JUAN 27-5 UNIT	Facility Type	Gas Well

Surface Owner	Federal	Mineral Owner	Federal	Lease No.	NMSF-079492A
---------------	---------	---------------	---------	-----------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	13	027N	005W	790	South	790	East	Rio Arriba

NATURE OF RELEASE

Type of Release	Fresh Water	Volume of Release	20 BBLS.	Volume Recovered	0 BBLS.
Source of Release	Mist Pump Tank	Date and Hour of Occurrence	11/23/2003	Date and Hour of Discovery	11/24/2003
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Date and Hour				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*
NA

Describe Cause of Problem and Remedial Action Taken.*
Vandals broke a fitting on the mist pump tank (Drake 27) allowing approximately 20 bbls of fresh water (no KCL added) to leak onto the ground. Vandals also opened a small drain on a diesel tank that leaked a small amount of diesel (approximately 5 gallons) onto the ground.

Describe Area Affected and Cleanup Action Taken.*
The diesel was contained on location. The small amount of impacted soils will be raked and mixed to promote natural remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION		
Printed Name:	Approved by District Supervisor:		
Title: Environmental Representative	Approval Date:		Expiration Date:
E-mail Address: lhasely@br-inc. com or gwurtz@br-inc.com	Conditions of Approval:		Attached
Date: 11/24/03 Phone: (505) 326-9841 or 9537			<input type="checkbox"/>

* Attach Additional Sheets If Necessary

NOG-F0332956198