

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	ConocoPhillips Company	Contact	Monica D. Rodahl
Address	5525 Hwy. 64, Farmington, NM 87401	Telephone No.	505-599-3458
Facility Name	Scott #1	Facility Type	Gas well
		API #30-045-13094	


Surface Owner	Fee	Mineral Owner	Fee	Lease No.	Fee
---------------	-----	---------------	-----	-----------	-----

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	2	T29N	R13W	2220	South	1450	West	San Juan

NATURE OF RELEASE

Type of Release	Volume of Release	Volume Recovered
Condensate	Estimated 5 BBL	none
Source of Release	Date and Hour of Occurrence	Date and Hour of Discovery
Underground tank overflowed due to detection system failure	6/18/2003	6/18/2003 - 1130 hr
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
	Alan & Gail McCulloch - 6/18/03 @ 1330 hr - via phone Denny Foust - OCD - 6/18/2003 @ 1600 hr - via email	
By Whom?	Date and Hour	
Monica D. Rodahl	6/18/2003 - 1600 hr	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* A high level / leak detection alarm failed on an underground condensate tank, causing the tank to overflow, resulting in an estimated 5 BBL spill. Lines were shut in and an emergency one-call was placed to excavate stained soils and investigate detection failure.		
Describe Area Affected and Cleanup Action Taken.*		
The area affected is on the Drake Ranch south of 30 th Street in Farmington. The landowner (Gail McCulloch) was promptly notified. Remediation will commence the morning of 6/19/03, with a final report to follow.		



I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Monica D. Rodahl</i>	OIL CONSERVATION DIVISION	
Printed Name: Monica D. Rodahl	Approved by District Supervisor: <i>Denny Foust</i> for Frank Chavez	
Title: Safety, Health, Environmental, & Regulatory Technician	Approval Date: 6/24/03	Expiration Date:
Date: 6/18/2003 Phone: 505-599-3458	Conditions of Approval:	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

n DGF0317554777