

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised March 17, 1999

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

30-045-13101 OPERATOR ☐ Initial Report ☒ Final Report

Name of Company Richardson Operating Company	Contact <input type="checkbox"/> John Durham
Address 3100 La Plata Highway, Farmington, NM 87401	Telephone No. <input type="checkbox"/> 564-3100
Facility Name Navajo H-5	Facility Type <input type="checkbox"/> Gas Producer

Surface Owner Navajo Tribe	Mineral Owner Navajo Tribe	Lease No. <input type="checkbox"/> 14-20-603-2198
----------------------------	----------------------------	---

LOCATION OF RELEASE

Unit Letter	Section 13	Township 29N	Range 14W	Feet from the 705	North/South Line South	Feet from the 660'	East/West Line West	County San Juan
-------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	--------------------

NATURE OF RELEASE

Type of Release Tank Overflow	Volume of Release 3 bbls	Volume Recovered <input type="checkbox"/>
Source of Release Production Water from Tank	Date and Hour of Occurrence 1/16/03 11:45 a.m.	Date and Hour of Discovery <input type="checkbox"/> 1/16/03 11:45 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Bruce Martin	
By Whom? <input type="checkbox"/> Lori McCabe	Date and Hour <input type="checkbox"/> 1/16/03 11:45 a.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Tank was not pulled the night before; caused the tank to become full and overflow; upon finding the tank overflowing our water truck pulled the tank immediately

Describe Area Affected and Cleanup Action Taken.\*

Area around tank ; evaporation

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>John Durham</i>	OIL CONSERVATION DIVISION	
Printed Name: John Durham	Approved by <input type="checkbox"/> District Supervisor: <i>Denny Kent</i> <i>For Frank Chavez</i>	
Title: Operations Manager	Approval Date: <i>3/20/03</i>	Expiration Date:
Date: 1/16/03 Phone: 564-3100	Conditions of Approval:	Attached <input type="checkbox"/>

\* Attach Additional Sheets If Necessary

NDGF 0307938616