

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report

☒ Final Report

Name of Company BP America Production Company	Contact Brittany Benko
Address 200 Energy Court Farmington, NM 87401	Telephone No. (505) 326-9235
Facility Name Kernaghan B 5	Facility Type Wellsite
Surface Owner BLM	Mineral Owner BLM
Lease No. 30-045-27338 NMSF - 078387A	

LOCATION OF RELEASE

Unit Letter A	Section 28	Township 31N	Range 8W	Feet from the 1210	North/South Line FNL	Feet from the 1115	East/West Line FEL	County San Juan County
-------------------------	----------------------	------------------------	--------------------	------------------------------	--------------------------------	------------------------------	------------------------------	----------------------------------

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 10 bbls	Volume Recovered 10 bbls
Source of Release Vent piping on blow case.	Date and Hour of Occurrence November 23, 2004 ????	Date and Hour of Discovery November 24, 2003 8:00 AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* The Field Tech was performing his normal duties and discovered a produced water release into the bermed area of the water pit. He re-piped the vent line to lessen the chance of future freezing.		
Describe Area Affected and Cleanup Action Taken.* The produced water was contained inside the berm on top of frozen ground. The Field Tech immediately called a truck and had the fluid picked up and transferred to another tank.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: <i>Brittany D Benko</i>	OIL CONSERVATION DIVISION	
Printed Name: Brittany D Benko	Approved by District Supervisor: <i>Denny Zent</i> <i>for Frank Chavez</i>	
Title: Environmental Coordinator	Approval Date: <i>12/11/03</i>	Expiration Date:
Date: 12/04/2003 Phone: (505) 326-9235	Conditions of Approval:	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

n DGF 0334 535 108

2



BP America Production Company

200 Energy Court
Farmington, NM 87401

Phone: (505) 326-9200

December 4, 2003

Bureau of Land Management
1235 La Plata Highway
Farmington, NM 87401
Attn: Mr. Mark Kelly

RE: Produced Water Release – Kernaghan B 5, Sec. 28, T31N, R 8W

Dear Mr. Kelly,

This letter is to inform you of a 10 barrel produced water release we had on the Kernaghan B 5 on 11/24/2003. The release was the result of a frozen vent line on the blow case piping. The piping separated and the produced water was released into the bermed area, and due to the frozen ground, all of the produced water was recovered. The vent line has been re-piped to lessen the chance of future freezing.

Should you have any additional questions, please feel free to contact me at 326-9235 in our Farmington office.

Sincerely,

Brittany D Benko
Environmental Coordinator

cc: New Mexico Oil Conservation Division
1000 Rio Brazos Rd
Aztec, NM 87410
Attn: Mr. Denny Foust