

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30-045-30058

OPERATOR

☐ Initial Report ☐ Final Report

Name of Company Richardson Operating Company	Contact <input type="checkbox"/> John Durham	
Address 3100 La Plata Highway, Farmington, NM 87401	Telephone No. <input type="checkbox"/> 564-3100	
Facility Name WF Federal 29-2	Facility Type <input type="checkbox"/> Gas Producer	
Surface Owner BLM	Mineral Owner BLM	Lease No. <input type="checkbox"/> NM-97843

LOCATION OF RELEASE

Unit Letter P	Section 29	Township 30N	Range 14W	Feet from the 795'	North/South Line SOUTH	Feet from the 665	East/West Line EAST	County SAN JUAN
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	--------------------

NATURE OF RELEASE

Type of Release Production Water	Volume of Release 3 bbls	Volume Recovered <input type="checkbox"/> 0
Source of Release Stuffing Box Leak	Date and Hour of Occurrence 01/18/03 12:00 a.m.	Date and Hour of Discovery <input type="checkbox"/> 01/18/03 1:30 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom? <input type="checkbox"/>	Date and Hour <input type="checkbox"/>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* Stuffing box tampered with; repair stuffing box to stop leak		
Describe Area Affected and Cleanup Action Taken.* area around stuffing box; evaporation		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: <u>John Durham</u>	OIL CONSERVATION DIVISION	
Printed Name: John Durham	Approved by <input type="checkbox"/> District Supervisor: <u>Denny Jant</u> <u>for Frank Chavez</u>	
Title: Operations Manager	Approval Date: <u>3/20/03</u>	Expiration Date:
Date: 01/21/03 Phone: 564-3100	Conditions of Approval:	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

n DGF0307941697

