

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

32045-30812

OPERATOR

☐ Initial Report ☐ Final Report

Name of Company Richardson Operating Company	Contact <input type="checkbox"/> John Durham	
Address 3100 La Plata Highway, Farmington, NM 87401	Telephone No. <input type="checkbox"/> 564-3100	
Facility Name Salty Dog 2	Facility Type <input type="checkbox"/> Water Injection Well	
Surface Owner BLM	Mineral Owner BLM	Lease No. <input type="checkbox"/> NMSF-079968

LOCATION OF RELEASE

Unit Letter J	Section 5	Township 29N	Range 14W	Feet from the 1495	North/South Line SOUTH	Feet from the 1477	East/West Line EAST	County SAN JUAN
------------------	--------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	--------------------

NATURE OF RELEASE

Type of Release Broken Line	Volume of Release 7bbls	Volume Recovered <input type="checkbox"/> 0
Source of Release Broken water line	Date and Hour of Occurrence 01/18/03 6:25 a.m.	Date and Hour of Discovery <input type="checkbox"/> 01/18/03 6:30 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Tried the OCD office in Aztec; no answer; hit star 8 - 2 for answering machine; no answer; not able to leave message	
By Whom? <input type="checkbox"/> John Durham	Date and Hour <input type="checkbox"/> 01/18/03 6:40 a.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Line broke at 6:25 a.m. due to vandalism; motor was tampered with; kill switch disabled; found @ 6:30 a.m. by pumper and well SI

Describe Area Affected and Cleanup Action Taken.*

Area around wellhead; evaporation

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>John Durham</u>	OIL CONSERVATION DIVISION	
Printed Name: John Durham	Approved by <input type="checkbox"/> District Supervisor: <u>Gerry Faint</u> <u>for Frank Chavez</u>	
Title: Operations Manager	Approval Date: <u>03/20/2003</u>	Expiration Date:
Date: 1/21/03 Phone: 564-3100	Conditions of Approval:	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

n 06F0308038386

