

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505


State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141

Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form



Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company	ConocoPhillips Company	Contact	Monica D. Olson
Address	5525 Hwy. 64, Farmington, NM 87401	Telephone No.	505-599-3458
Facility Name	San Juan 29-5 Unit #38	Facility Type	Producing Gas Well
Surface Owner	State	Mineral Owner	Federal
		Lease No.	NM NM-78415A
		API #30-039-07472	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	32	T29N	R5W	860'	South	1115'	West	Rio Arriba

Latitude 36° 22' 38" Longitude 107° 23' 9"

NATURE OF RELEASE

Type of Release - Natural Gas	Volume of Release - 55 MCF	Volume Recovered - none
Source of Release: Backhoe hit wellhead	Date and Hour of Occurrence 7/12/04 - 12:30 p.m.	Date and Hour of Discovery 7/12/04 - 12:30 p.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Denny Foust - OCD - 7/12/04 via email Mark Kelly - BLM - 7/12/04 via email	
By Whom? Monica Olson	Date and Hour - 7/12/04 - 5:00 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* **While excavating a line on location, a backhoe struck the nipple on the wellhead, causing an approximate 55 MCF gas release to the atmosphere. The well was flowing out a 1/4" orifice at approximately 172 psi (absolute pressure) (161 gauge) and it blew for about 5 hours before a pump truck arrived on location to kill the well.**

Describe Area Affected and Cleanup Action Taken.* **The area was evacuated and a truck was called out to pump water down the well to kill the well in order to make repairs to the wellhead. Unless changes in the report are necessary, this will be the final report.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Monica D. Olson</i>	OIL CONSERVATION DIVISION	
Printed Name: Monica D. Olson	Approved by District Supervisor: <i>For Frank Chavez</i> <i>Denny Foust</i>	
Title: Safety, Health, Environmental, & Regulatory Technician	Approval Date: 8/02/04	Expiration Date:
E-mail Address: monica.olson@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 7/12/04 Phone: 505-599-3458		

* Attach Additional Sheets If Necessary

n DGF 042/534994