

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action Div.

OPERATOR

Name of Company	ConocoPhillips Company	Contact	Monica D. Olson
Address	5525 Hwy. 64, Farmington, NM 87401	Telephone No.	505-599-3458
Facility Name	Jicarilla A #14	Facility Type	Producing Gas Well
Surface Owner	Jicarilla Tribe	Mineral Owner	Federal
		Lease No.	JIC105
			API # 30-039-20629

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	24	T26N	R4W	1186'	North	1160'	East	Rio Arriba

Latitude 36.47621° Longitude 107.19775°

NATURE OF RELEASE

Type of Release – Condensate & produced water	Volume of Release – 60 BBL condensate, 44 BBL produced water	Volume Recovered - none
Source of Release: Vandalism - drain valve opened	Date and Hour of Occurrence 12/21/04	Date and Hour of Discovery 12/21/04 – 10:45 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Keith Manwell – Jicarilla EPO – via fax Denny Foust – OCD – via email Fred Vigil – Jicarilla Oil & Gas Administration – via voice mail Bryce Hammond, Herman Lujan, Mark Kelly – BLM – via email	
By Whom? Monica Olson	Date and Hour – 12/21/04 – 12:00 p.m. via e-mail / fax / voice mail	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* A spill of 60 BBL condensate and 44 BBL produced water was discovered on Tuesday morning, 12/21/04. The seal on the 4" drain valve on the condensate tank had been broken and the valve opened, apparently due to an act of vandalism. All spilled fluids were contained within the berm. This was reported to the Jicarilla Apache Police Department and the well was shut in until the investigation and cleanup are completed.

Describe Area Affected and Cleanup Action Taken.* All spilled condensate remained within the berm, but probably soaked down into the soil. Remediation activities will likely start on Tuesday, 12/28/04. All stained soil will be excavated and taken to the Envirotech landfarm and backfilled with dirt from an approved Jicarilla site. Unless other details are discovered during remediation, this will be the final report.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Monica D. Olson	OIL CONSERVATION DIVISION	
Printed Name: Monica D. Olson	Approved by District Supervisor: Denny Foust for Charlie Penning	
Title: Safety, Health, Environmental, & Regulatory Technician	Approval Date: 12/27/04	Expiration Date:
E-mail Address: monica.olson@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 12/21/04	Phone: 505-599-3458	

* Attach Additional Sheets If Necessary

NDG-F0436254561