

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30 039 27055

OPERATOR

X Initial Report

Final Report

Name of Company Williams Production Company, LLC	Contact Olivia McNamara
Address One Williams Center	Telephone No. 918/573-5314
Facility Name Rosa SWD #1	Facility Type: salt water disposal well, currently being drilled

Surface Owner BLM	Mineral Owner	Lease No.
-------------------	---------------	-----------

LOCATION OF RELEASE

Unit Letter	Section 23	Township 31N	Range 6W	Latitude	Longitude	County Rio Arriba		
-------------	---------------	-----------------	-------------	----------	-----------	----------------------	--	--

NATURE OF RELEASE

Type of Release produced water	Volume of Release approx. 160 barrels	Volume Recovered 120 barrels
Source of Release Frac Tank valve	Date and Hour of Occurrence 10/20/2004, 4 PM	Date and Hour of Discovery 10/20/2004, 4 PM
Was Immediate Notice Given? X Yes No Not Required	If YES, To Whom? Frank Chavez	
By Whom? Olivia McNamara	Date and Hour 10/21/2004, 10 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes X No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* Frac tank valve was leaking. When it was tightened, it broke allowing a release. A vac truck was on site at the time of the incident and removed as much of the free liquids as possible. The faulty valve has been replaced.

Describe Area Affected and Cleanup Action Taken.* The area impacted includes a portion of the location and a nearby road. Although most of the water was recovered, a minimal amount left the location and ran down the road. A sample has been taken of the water to help us define our remediation. If the levels of chlorides require treatment, the impacted soil will be treated in place with gypsum. This water was flow back water and we do not expect the tests to show high levels of any contaminants.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Olivia McNamara</i>	OIL CONSERVATION DIVISION	
Printed Name: OLIVIA MCNAMARA	Approved by <input type="checkbox"/> District Supervisor: <i>Denny Jent</i> for Frank Chavez	
Title: EHS SPECIALIST	Approval Date: 11/03/04	Expiration Date:
Date: 10/25/04 Phone: 918/573-5314	Conditions of Approval:	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

11 DGF0429553492