

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised June 10, 2003

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30 039 27436

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Burlington Resources	Contact	Bruce Gantner
Address	P.O. Box 4289 Farmington NM 87499	Telephone No.	(505) 326-9700
Facility Name	SAN JUAN 27-4 UNIT	Facility Type	Gas Well
Surface Owner	Federal	Mineral Owner	Federal
Lease No.	NMSF-080675		

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	34	027N	004W	1110	North	1940	East	Rio Arriba

NATURE OF RELEASE

Type of Release	Condensate/Produced Water	Volume of Release	10 BBLS.	Volume Recovered	8 BBLS.
Source of Release	Tank Overflow do to ruptured diaphragm on sep	Date and Hour of Occurrence	12/17/2004	Date and Hour of Discovery	12/20/2004 12:45:00 PM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Denny Foust		
By Whom?	Bruce Gantner	Date and Hour	12/20/2004 1:15:00 P		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	0		

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The diaphragm on the dump valve on the separator ruptured causing fluids to dump to the tank only resulting in eventual overflow of the tank. Truck was sent to recovered spilled fluids and 8 bbls were recovered. Impacted soils were raked to extent possible given frozen conditions.

Describe Area Affected and Cleanup Action Taken.*

Within tank berm only.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION		
Printed Name:	Denny Foust		
Title: Environmental Representative	Approved by District Supervisor:	for Charlie Perrin Actg	
E-mail Address: lhasely@br-inc. com or gwurtz@br-inc.com	Approval Date:	12/27/04	Expiration Date:
Date: 12/21/04	Phone: (505) 326-9841 or 9537	Conditions of Approval:	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

106F0436255456