District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Avenue, Artesia, NM 88210

District III

1000 Rio Brazos Road, Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action " S										
					OPERATOR SAN Initial Report Final Report					
Name of Company Lance Oil & Gas, Inc.						Contact Jo Becksted Tolonhoro No. (505) 508 5601 Feb 58				
Address P. O. Box 70 Facility Name Cha Cha #24						Telephone No. (505) 598-5601 Ext. 58 Facility Type Oil & Gas Water Injection Line				
- unity - unity One one nat						Tuesday 1 jpc On to Gus Water injection Diffe				
Surface Owner Navajo Tribe Mineral Owner						Navajo Tribe Lease No. 14-20-603-2199				
				LOCA	NOF RELEASE API 30.045-07990					
Unit Letter	Section	Township	Range	Feet from the	North/	South Line	Feet from the	East/V	Vest Line	County
I	21	29N	14W	1760	:	South	835	East		San Juan
			Lat	titude	_ Longitud	e	-			
NATURE OF RELEASE										
Type of Release Produced Water										ecovered 0
Source of Release Steel water line									Date and Hour of Discovery 10/9/04 @ approx 7:30 a.m.	
Was Immediate Notice Given?						If YES, To Whom?			арргох 7.30 а.п	
☐ Yes ☐ No ☒ Not Required						N/A				
By Whom? N/A						Date and Hour N/A				
Was a Watercourse Reached? ☐ Yes ☑ No						If YES, Volume Impacting the Watercourse. N/A				
If a Watercourse was Impacted, Describe Fully.*										
N/A										
Describe Cause of Problem and Remedial Action Taken.*										
Old steel water line ruptured and leaked. Wells in the field were shut in until leak could be repaired with 300' of new steel water lines.										
of soos water the ruptured and leaked. Wens in the field were shut in until leak could be repaired with 500. Of new steel water lines.										
Describe Area Affected and Cleanup Action Taken.*										
The area surrounding the Cha Cha #24 well site and soil from the wellsite, at which point the spill was contained. All of the effected soil will be scraped up and will be land farmed.										
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and										
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger										
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health										
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other										
federal, state, or local laws and/or regulations.										
	\frown	2.1	1		OIL CONSERVATION DIVISION					
Signature:		Bleu	1		Deny ten					
Printed Name	: Jo Beck	sted			Approved by District Supervisor: for Frank Chavez					
Title: Compliance Administrator						Approval Date: /0/20/04 Expiration Date:				
E-mail Addre	ss: jbecks	te@westernga			Conditions of Approval: Attached					
Date: Octo	ber 11, 20	04 P	5) 598-5601 Ext. 5	58	Transies					