

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report


Name of Company	ConocoPhillips Company	Contact	Monica D. Rodahl
Address	5525 Hwy. 64, Farmington, NM 87401	Telephone No.	505-599-3458
Facility Name	Kate Standage #1	Facility Type	Gas well
		API #30-045-09648	
Surface Owner	Fee	Mineral Owner	Fee
		Lease No.	Fee

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	12	T30N	R12W	1470	South	1525	East	San Juan

NATURE OF RELEASE

Type of Release	Condensate	Volume of Release	Estimated 5 BBL	Volume Recovered	none
Source of Release	Leak in 2" drain valve on condensate tank	Date and Hour of Occurrence	6/18/2003	Date and Hour of Discovery	6/18/2003 - 1300 hr
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Denny Foust - OCD - 6/18/2003 @ 1600 hr - via email		
By Whom?	Monica D. Rodahl	Date and Hour	6/18/2003 - 1600 hr		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.* The 2" drain valve (plug type) on the condensate tank was leaking. It was swedged to a 3" line that was only connected hand-tight, resulting in the spill of an estimated 5 BBL. Well was shut in and valve and swedge were repaired.					
Describe Area Affected and Cleanup Action Taken.* All spilled liquids remained within the bermed area. The spill resulted in an affected area of 9'x7'x2' with more area suspected to be affected under the tank (investigation pending). Remediation will commence the morning of 6/19/03, with a final report to follow.					



I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	Monica D. Rodahl	OIL CONSERVATION DIVISION	
Printed Name:	Monica D. Rodahl	Approved by District Supervisor:	Denny Foust for Frank Chavez
Title:	Safety, Health, Environmental, & Regulatory Technician	Approval Date:	6/24/03
Date:	6/18/2003	Phone:	505-599-3458
		Expiration Date:	
		Conditions of Approval:	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

11 DGF0317555475