

District I - (505) 393-6161

P.O. Box 1940

Hobbs, NM 88241-1980

District II - (505) 748-1283

811 South First

Artesia, NM 88210

District III - (505) 334-6178

1000 Rio Brazos Road

Aztec, NM 87410

District IV - (505) 827-7131

# State of New Mexico

## Energy Minerals and Natural Resources Department

### Oil Conservation Division


2040 South Pacheco Street

Santa Fe, New Mexico 87505

(505) 827-7131

Form C-141

Originated 2/13/97



Submit 2 copies to:  
Appropriate District  
Office in accordance  
with Rule 116.

#### Release Notification and Corrective Action

3004524516

#### OPERATOR

☐ Initial Report

☒ Final Report

Name: Burlington Resources	Contact: GREGG WURTZ
Address: P.O. Box 4289 Farmington NM 87499	Telephone No.: (505) 326-9537
Facility Name: ANGEL PEAK 23E	Facility Type: Gas Well

Surface Owner: Fed.	Mineral Owner: Fed	Lease Number: NMSF-047017-A
---------------------	--------------------	-----------------------------

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet From the	North/South Line	Feet From the	East/West Line	County: San Juan
O	10	028N	011W	955	South	1725	East	

#### NATURE OF RELEASE

Type of Release: 15 bbl Produce water/ 0.5 bbl condensate	Volume of Release: 15.5 BBLS.	Volume Recovered: 0 BBLS.
Source of Release: Production Storage Tank	Date and Hour of Occurrence: 8/4/2003	Date and Hour of Discovery: 8/4/2003
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If Yes, To Whom? <del>Denny Foust</del>	
By Whom? Gregg Wurtz	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. 0	

If a Watercourse was Impacted, Describe Fully. (Attach Additional Sheets If Necessary)

None impacted

Describe Cause of Problem and Remedial Action Taken. (Attach Additional Sheets If Necessary)

Drain plug for tank was damaged by corrosion and leaked.

Describe Area Affected and Cleanup Action Taken. (Attach Additional Sheets If Necessary)

Fluids were contained within the bermed area. Soils impacted were raked insitu to promote natural remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Gregg Wurtz</i>	OIL CONSERVATION DIVISION	
Printed Name: Gregg Wurtz	Approved by: <i>Denny Foust</i> District Supervisor: <i>for Frank Chavez</i>	
Title: Environmental Representative	Approval Date: 8/13/03	Expiration Date:
Date: 8-06-03 Phone: (505) 326-9841 or 326-9842	Conditions of Approval:	Attached: <input type="checkbox"/>

NDG-F0322531746