District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe. NM 87505

Form C-141 Revised June 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action .								
30 039 07554	<u> </u>	OPE	CRATOR	L. K.	Initial	Rèport 🔽	Final Report	
Name of Company Burlington Resources			Ed Has	sely Sely	MENE SU	N. C.		
Address P.O. Box 4289 Farmington NM 87499			Telephone No. (505) 326-9700					
Facility Name SAN JUAN 29-7 UNIT 72			Type Gas W	ell	<u> </u>	· · · · · · · · · · · · · · · · · · ·		
Surface Owner Fee Mineral Owner			Fee		Lease No.	FE	E .	
LOCATION OF RELEASE								
Unit Letter Section Township Range Feet from the	North/Sout		Feet from the	East/West Lin	e County	Rio Arriba		
B 26 029N 007W 800	Nor	th	1800	East		Kio Airiba		
NATURE OF RELEASE								
Type of Release Condensate		Volume	of Release	175 BBLS.	Volume Re	covered	95 BBLS.	
Source of Release Storage Tank			Date and Hour of Occurence 3/7/2004 7:00:00 AM  Date and Hour of Discovery 3/7/2004 7:00:00 AM 3/7/2004 7:00:00 AM					
Was Immediate Notice Given? ✓ Yes ☐ No ☐ Not Required			T 117 0	nny Foust	·			
By Whom? Ed Hasely			Date and Hour 3/8/2004 7:40:00 AM					
Was a Watercourse Reached? ☐ Yes ✓ No			If YES, Volume Impacting the Watercourse.					
If a Watercourse was Impacted, Describe Fully.*		<u> </u>		<del></del>	<del></del>			
NA			•					
	•							
Describe Cause of Problem and Remedial Action Taken.*								
An employee for Giant thought he was unscrewing a bull plug on the load valve of the condensate storage tank, but instead unscrewed the valve								
apart. The contents of the storge tank drained out into the bermed area.								
Describe Area Affected and Cleanup Action Taken.*			<u> </u>		•			
All fluids were contained inside the bermed area. The free liquids were recovered w/ a vacuum truck. The condensate tank and the pit tank were								
removed and the impacted soils were excavated and landfarmed onsite.								
					•			
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and								
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their								
operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal,								
state, or local laws and/or regulations.	eport does ii	ot renev	· · ·	responsibility	ioi compita		inci iederai,	
Signatura			OIL CON	CEDVATIO	N DIVICE	ON		
Signature: So Those Some OIL CONSERVATION DIVISION								
Printed Name:	Approved by	District	Supervisor:	eny	- /0			
Led Hasely			to	r Foton	1K C	have	۲.	
Title: Environmental Representative	Approval Da	te: ح	3/18/04	L E	xpiration Da	te:		
E-mail Address: lhasely@br-inc. com or gwurtz@br-inc.com	Conditions o	f Approv	al: / 1		A	Attached		
Date: 3/11/04 Phone: (505) 326-9841or 9537.							]	