District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue. Artesia. NM 88210
District III
1000 Rio Brazos Road. Aztec. NM 87410
District IV

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe. NM 87505 Form C-141 Revised June 10, 2003

AUG 2004 Submit-2 Copies to appropriate
District Office in accordance
With Rule 116 on back
side of form

1220 S. St. Franc	is Dr., Sar	nta Fe, NM 8	37505		Sa	nta Fe	. NM 8750	ر يونيا 55	CAS!	: 5 ON		side of form	
<u> </u>	\sim	29 Ω	UU 1	Release	Notifica		and Corre	ctive Act	2 O > -	1164-11; 2		Final Danast	
30 039 24470									A COLOR	∐{Initial	Report 🗸	Final Report	
							Contact Ed Hasely						
							Telephone No. (505) 326-9841						
Facility Name	SAN J	UAN 30-6 1	UNIT		478	Facility Type Gas Well							
Surface Owner	Fee			M	. Fee		Le	ase No.		FEE			
					LOCAT	ION	OF RELE	CASE					
Unit Letter	tter Section Township Range Feet from the North/So			h Line Feet from the East/West Line			t Line	County					
A	A 29 030N 006W 860 No				th	n 985 East Rio Arriba)a		
NATURE OF RELEASE													
Type of Release Fruitland Coal Produced Water							Volume of Release 6 BBLS. Volume Recovered 0 BBLS.						
Source of Release Wellhead							Date and Hour of Occurence B/3/2004 Date and Hour of Discovery 8/3/2004						
Was Immediate Notice Given? ☐ Yes ☐ No ✔ Not Required							If YES, To Whom?						
By Whom?							Date and Hour						
Was a Watercourse Reached?							If YES, Volume Impacting the Watercourse.						
If a Watercourse	e was Impa	acted, Descri	be Fully.	k				•					
NA													
				•									
Describe Cause	of Probler	n and Remed	tial Actio	n Taken *									
Describe Cause of Problem and Remedial Action Taken.* An unknown person closed the 2" ball valve and opened a 1" bleeder valve on the pumping well. Fruitland Coal produced water was pumped out													
of the opened bleeder valve onto location. The operator was on location two days prior and all was working OK. Suspect intentional foul play.													
or are opened ordered. The opened was on received into any prior and an was nothing ord suspect intelligible play.													
Describe Area A		-											
The water soaked into the ground on location. If needed, the area will be raked upon drying to break up any crust that may form.													
•													
				ve is true and cor									
				and/or file certai								endanger public bility should their	
operations have	failed to a	dequately in	vestigate	and remediate co	ntamination	that pose	a threat to g	round water, si	urface v	vater, hur	nan health or	r the	
environment. state, or local la				ce of a C-141 r	eport does n	ot reliev	e the operato	r of responsib	oility fo	or complia	ince with any	y other federal,	
biato, or room.		1450101101101	<u> </u>										
Signature: (111	h					OIL CO	<u> NSERVA</u>	ΓΙΟΝ	DIVISI	ON —		
4	1/6	sal 1						Hen	1H	10	en		
Printed Name:	Fall	tecol			Approved by	District	Supervisor:		9	.1/ 0	- 1000	<i>P</i> 7	
Title: Environn	nental Ren	resentative	/		Approval Da	nte:	en t	tor F	Fyn	iration Da	ite:	L 2	
						. ?	3/05/	04	Lyp				
E-mail Address	• •	br-inc. com o	or gwurtz	@br-inc.com	Conditions of	of Approv	aķ. /			l A	Attached		
Date: 8/3/C	۶ <u>۴</u> (Phone: (505)	326-984	lor 9537									