

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report ☐ Final Report ☒

Name of Company BP America Production Company	Contact Brittany Benko
Address 200 Energy Court Farmington, NM 87401	Telephone No. (505) 326-9235
Facility Name Florance AE 1	Facility Type Wellsite

Surface Owner BLM	Mineral Owner BLM	Lease No. 30-045-09108
--------------------------	--------------------------	-------------------------------

LOCATION OF RELEASE

Unit Letter M	Section 25	Township 30N	Range 10W	Feet from the 870	North/South Line FSL	Feet from the 809	East/West Line FWL	County San Juan County
-------------------------	----------------------	------------------------	---------------------	-----------------------------	--------------------------------	-----------------------------	------------------------------	----------------------------------

NATURE OF RELEASE

Type of Release Produced Water/Sand	Volume of Release 25 bbls	Volume Recovered 25 bbls
Source of Release Flowback Tank	Date and Hour of Occurrence February 27, 2004 3:00 PM	Date and Hour of Discovery February 27, 2004 3:45 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Denny Foust (Left message at 8:00 am at 320-0200)	
By Whom? Brittany Benko	Date and Hour 02/28/2004 8:00 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Riley Industrial had just finished cleaning the flowback tank. The task was complete and the vacuum truck was running. The Riley supervisor told the operator to shut down the truck. When the operator went to release the vacuum seal for the hose on the truck, the wrong lever was pushed, which opened the rear unit resulting in a spill of approximately 25 barrels. The lever was immediately reversed to shut the lid. None of the spilled material left the location.

Describe Area Affected and Cleanup Action Taken.*

The spilled material was contained and cleaned up with the vacuum truck immediately. The spilled material was taken to Basin Disposal.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Brittany D Benko</i>	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Brittany D Benko	Approved by District Supervisor: <i>Denny Foust for Frank Chavez</i>	
Title: Environmental Coordinator	Approval Date: 3/15/04	Expiration Date:
Date: 03/10/2004 Phone: (505) 326-9235	Conditions of Approval:	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

NDGF0406342852