

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30 045 31169

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company	Richardson Operating Company	Contact	Tom Bergin
Address	3100 La Plata Hwy, Farmington, NM 87401	Telephone No.	(505) 564-3100
Facility Name	NV Navajo 26-4	Facility Type	Gas Well

Surface Owner	Navajo Tribe	Mineral Owner	Navajo Tribe	Lease No.	14-20-603-2172
---------------	--------------	---------------	--------------	-----------	----------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N/A	26	29N	14W	1085	South	800	East	San Juan

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Rust	Volume of Release	50'X30', 1/4" deep	Volume Recovered	All
Source of Release	Air Pack	Date and Hour of Occurrence	7-24-04 @ 1:00 p.m.	Date and Hour of Discovery	8/2/04 @ 11:00 a.m.
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully



Describe Cause of Problem and Remedial Action Taken.*

Was cleaning out frac sand in wellbore with air pac, had blow line to pit. Overspray on north side of pit caused rust residue on ground. Will build baffle for blow line.

Describe Area Affected and Cleanup Action Taken.*

Rust residue was 30' X 50' area on north side of pit, 1/4" deep - scraped off and put in pit.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Tom Bergin	Approved by District Supervisor: 	
Title: Operations Superintendent	Approval Date: 8/05/04	Expiration Date:
E-mail Address: ropcorpc@digii.net	Conditions of Approval:	Attached <input type="checkbox"/>
Date: August 3, 2004 Phone: (505) 564-3100		

* Attach Additional Sheets If Necessary

10GF0421853228

