



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/II/3district.htm>

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test 11-1-10 Operator Enervest API #30-0 39-06593
Sicrilla
Property Name Apache 102 Well No. 1206 Location: Unit _____ Section 9 Township 24N Range 4W
Well Status (Shut-In or Producing) Tubing 78 Intermediate 0 Casing 85 Bradenhead 8

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	INTERMEDIATE	CASING		
5 minutes	<u>0</u>	<u>85</u>	Steady Flow _____	
10 minutes	<u>0</u>	<u>88</u>	Surges _____	
15 minutes	<u>0</u>	<u>90</u>	Down to Nothing <u>✓</u>	
20 minutes	<u>0</u>	<u>92</u>	Nothing _____	<u>✓</u>
25 minutes	<u>0</u>	<u>92</u>	Gas <u>✓</u>	
30 minutes	<u>0</u>	<u>92</u>	Gas & Water _____	
			Water _____	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

By Allen Cochran
lease Operator
(Position)

Witness _____

