



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
[http://emnrd.state.nm.us/ocd/District III/district.htm](http://emnrd.state.nm.us/ocd/District%20III/district.htm)

**BRADENHEAD TEST REPORT**

(submit 2 copies to above address)

Date of Test 9/14/10 Operator ENERVEST API #30-0 3923340  
Property Name Lie Cmt 147 Well No. 54 Location: Unit 9 Section 7 Township 25N Range 5W  
Well Status (Shut-In or Producing) Tubing 54 Intermediate NA Casing 150 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

| TIME       | PRESSURES:   |            | BRADENHEAD FLOWED | INTERMEDIATE FLOWED |
|------------|--------------|------------|-------------------|---------------------|
|            | INTERMEDIATE | CASING     |                   |                     |
| 5 minutes  |              | <u>150</u> | Steady Flow       |                     |
| 10 minutes |              | <u>5</u>   | Surges            |                     |
| 15 minutes |              | <u>150</u> | Down to Nothing   |                     |
| 20 minutes |              | <u>5</u>   | Nothing <u>✓</u>  |                     |
| 25 minutes |              | <u>5</u>   | Gas               |                     |
| 30 minutes |              | <u>150</u> | Gas & Water       |                     |
|            |              |            | Water             |                     |

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE \_\_\_\_\_

REMARKS: BAD 1" valve needed to replace (Replaced)

By Dince Montoya  
FIELD TECH  
(Position)

Witness \_\_\_\_\_

