

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Burlington Resources, a Wholly Owned Subsidiary of ConocoPhillips Company	Contact	Kelsi Gurvitz
Address	3401 E. 30th St., Farmington, NM 87402	Telephone No.	505-599-3403
Facility Name	Reese Mesa 104	Facility Type	Gas Well API #3004526976
Surface Owner	Federal	Mineral Owner	Federal
		Lease No.	NMNM-9037

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	12	32N	08W	840'	N	1465'	E	San Juan

Latitude **36.99778° N** Longitude **107.62253° W**

NATURE OF RELEASE

Type of Release – Produced Water	Volume of Release – 45 BBL	Volume Recovered – 40 BBL
Source of Release: Water Tank	Date and Hour of Occurrence unknown	Date and Hour of Discovery 4/13/10 2:30 p.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Brandon Powell, NMOCD- verbal and email RCVD APR 30 '10	
By Whom? Kelsi Gurvitz	Date and Hour – 4/14/10 2:50 p.m.	OIL CONS. DIV.
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. DIST. 3	
If a Watercourse was Impacted, Describe Fully.*		

Describe Cause of Problem and Remedial Action Taken.* **On April 13, 2010, it was discovered that the water tank had begun to overflow due to inaccessible roads. Upon discovery, the well was shut in and a water truck was called to location.**

Describe Area Affected and Cleanup Action Taken.* **All fluid remained on location and within the berm. Approximately 40 BBL of fluid was recovered. COPC will assess the impacted area and remediate, if needed.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Kelsi Gurvitz</i>	OIL CONSERVATION DIVISION	
Printed Name: Kelsi Gurvitz	Approved by District Supervisor: <i>Brandon Powell</i> For LCP	
Title: Environmental Consultant	Approval Date: 9/27/10	Expiration Date:
E-mail Address: kelsi.m.gurvitz@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 4/28/10 Phone: 505-599-3403		

* Attach Additional Sheets If Necessary

nBP1027052092