

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

MAY 20 2011

Farmington Field Office
Bureau of Land Management

Sundry Notices and Reports on Wells

1. Type of Well
GAS

2. Name of Operator
BURLINGTON
RESOURCES OIL & GAS COMPANY LP


3. Address & Phone No. of Operator

PO Box 4289, Farmington, NM 87499 (505) 326-9700

4. Location of Well, Footage, Sec., T, R, M

Unit D (NWNW), 1190' FNL & 790' FWL, Section 13, T27N, R6W, NMPM

5. Lease Number
SF-079363
6. If Indian, All. or
Tribe Name
7. Unit Agreement Name
San Juan 28-6 Unit
8. Well Name & Number
San Juan 28-6 Unit 194
9. API Well No.
30-039-20897
10. Field and Pool
Blanco South Pictured Cliffs
11. County and State
Rio Arriba, NM



12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission

Type of Action

☐ Notice of Intent

☒ Abandonment

☐ Change of Plans

☐ Other -

☒ Subsequent Report

☐ Recompletion

☐ New Construction

☐ Final Abandonment

☐ Plugging

☐ Non-Routine Fracturing

☐ Casing Repair

☐ Water Shut off

☐ Altering Casing

☐ Conversion to Injection

13. Describe Proposed or Completed Operations

The subject well was P&A'd on 5/2/11 per the attached report.

14. I hereby certify that the foregoing is true and correct.

Signed Crystal Tafoya Crystal Tafoya

Title: Staff Regulatory Technician

Date 5/20/11

(This space for Federal or State Office use)

APPROVED BY _____ Title _____ Date _____

CONDITION OF APPROVAL, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

ACCEPTED FOR RECORD

MAY 23 2011

FARMINGTON FIELD OFFICE

NMOCD *PC*

PC

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979

Farmington, New Mexico 87499

505-325-2627 * fax: 505-325-1211

Burlington Resources Oil & Gas Company LP

San Juan 28-6 Unit #194

April 18, 2011

Page 1 of 1

1190' FNL & 790' FWL, Section 13, T-27-N, R-6-W

Rio Arriba County, NM

Lease Number: SF-079363

API #30-039-20897

Plug and Abandonment Report

Notified NMOCD and BLM on 4/11/11

Plug and Abandonment Summary:

- 4/12/11 MOL. LO/TO equipment. Open up well and blow down 12 PSI bradenhead pressure. ND wellhead. NU 2-7/8" head with BOP, test. Round trip 1-11/16" bar with 2-1/4" gauge ring to 3070'. RIH with 2-7/8" wireline set CIBP and set at 3052'. Tally and TIH with 1-1/4" IJ tubing; tag BP at 3052'. SI well. SDFD.
- 4/13/11 Open up well; no pressure. Load casing with 2.5 bbls of water. Circulate well clean with additional 16 bbls of water. Attempt to pressure test casing; leak 1-1/4 bpm at 600 Psi. **Plug #1** with CIBP 3052', spot 22 sxs Class B cement (25.96 cf) with 2% CaCl₂ inside casing from 3052' to 2254' to cover the Pictured Cliffs interval through the Ojo Alamo top. PUH and WOC. TIH and tag cement low at 2337'. Attempt to pressure test casing; leak 1-1/4 bpm at 600 PSI. M. Gilbreath, BLM, required Plug #1a. **Plug #1a** spot 10 sxs Class B cement (11.8 cf) inside casing from 2337' to 1974' to cover the Ojo Alamo top. SI well and WOC. SDFD.
- 4/14/11 Open up well; no pressure. TIH and tag cement at 2110'. Attempt to pressure test casing; leak 1-1/4 bpm at 600 PSI. Perforate 3 squeeze holes at 1205'. RIH and set wireline CR at 1155'. Attempt to pressure test casing; leak 2 bpm at 700 PSI. **Plug #2** with CR at 1155' mix 59 sxs Class B cement (69.62 cf), squeeze 50 sxs outside 2.875" casing and leave 9 sxs inside casing to cover the Nacimiento top. TOH and LD tubing. SI well and WOC. SDFD.
- 4/18/11 Open up well, no pressures. Tag cement at 936'. TOH and LD tubing. Attempt to pressure test casing; leak. Perforate 3 squeeze holes at 174'. Establish circulation with 6 bbls of water. **Plug #3** spot 97 sxs Class B cement (114.46 cf) down 2.875" casing from 174' to surface, circulate good cement out bradenhead. ND BOP. Dig out wellhead. Issue Hot Work Permit. Monitor atmosphere. Cut off wellhead. Found cement down 90' in the casing and 50' in the annulus. **Plug #4** spot 41 sxs Class B cement (48.38 cf) to top off casing, annulus and install P&A marker. RD. Remove LO/TO. MOL.

Jimmy Morris, MSCI representative, was on location.

Oscar Torres, BLM representative, was on location.

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979

Farmington, New Mexico 87499

505-325-2627 * fax: 505-325-1211

Burlington Resources Oil & Gas Company LP

San Juan 28-6 Unit #194

May 2, 2011

Page 1 of 1

1190' FNL & 790' FWL, Section 13, T-27-N, R-6-W

Rio Arriba County, NM

Lease Number: SF-079363

API #30-039-20897

Plug and Abandonment Report

Notified NMOCD and BLM on 4/27/11

Plug and Abandonment Summary:

4/28/11 MOL. LO/TO equipment. Bust cement out of cellar. Issue Hot Work Permit. Cut off market and 1' of 8.625" casing. Expose 2.875" casing. Weld 2.875" collar on 2.875" casing. RU rig. NU 2.875" head and BOP, test. Tally 6 – 2.25" drill collars. TIH with collars and 2.25" blade bit with swivel. Drill good cement from surface to 54'. Note: soft void from 29' to 35'. LD 2 collars and RD drilling equipment. Pressure test 2.875" casing to 800 PSI, held OK for 5 minutes. SI well. SDFD.

5/2/11 Open up well; no pressure. TIH with 1.25" tubing and subs, tag cement at 54'. Load the hole with ¼ bbl of water.

Plug #1 spot 15 sxs Class B cement (17.7 cf) inside casing from 54' to surface, circulate good cement to pit out the casing valve.

TOH and LD 1 joint and subs. ND BOP.

Plug #2 spot 20 sxs Class B cement (23.6 cf) to top off casing, annulus and install P&A marker.

RD. Cut off 2 anchors and leave 2 due to high weeds. Remove LO/TO.

Jimmy Morris, MVCI representative, was on location.

Oscar Torres and John Coy, BLM representatives, were on location.