

P
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

*Risk
Plume
definition*

Submit 1 copy to
appropriate
District Office
and 1 copy to
the Santa Fe Office

(Revised 3/9/94)

PIT REMEDIATION AND CLOSURE REPORT

Operator: Meridian Telephone: _____

Address: 30-039 06996

Facility Or: San Juan 27-5 Unit #50 M.V., Meter 72604

Well Name _____

Location: Unit or Qtr/Qtr Sec G Sec 19 T 27 R 05 County Rio Arriba

Pit Type: Separator _____ Dehydrator X Other _____

Land Type: BLM _____, State _____, Fee X Other _____

Pit Location: Pit dimensions: length 12', width 12', depth 2'
(Attach diagram)

Reference: wellhead X, other _____

Footage from reference: 64'


Direction from reference: 315 Degrees X East North _____
of
_____ West South _____

Depth To Ground Water (Vertical distance from contaminants to seasonal high water elevation of ground water.)	Less than 50 feet	(20 points)
	50 feet to 99 feet	(10 points)
	Greater than 100 feet	(0 points) <u>10</u>

Wellhead Protection Area: (Less than 200 feet from a private domestic water source, or; less than 1000 feet from all other water sources.)	Yes (20 points)
	No (0 points) <u>0</u>

Distance To Surface Water: (Horizontal distance to perennial lakes, ponds, rivers, streams, creeks, irrigation canals and ditches.)	Less than 200 feet	(20 points)
	200 feet to 1000 feet	(10 points)
	Greater than 1000 feet	(0 points) <u>0</u>

RANKING SCORE (TOTAL POINTS): 10



Date Remediation Started: 03/21/95 Date completed: 03/21/95

Remediation Method: Excavation Approx. cubic yards

(Check all appropriate sections.)

Landfarmed Insitu Bioremediation

Other Backfill Pit Without Excavation

Remediation Location: Onsite N/A Offsite N/A
(i.e. landfarmed onsite, name and location of offsite facility)

General Description of Remedial Action: No line markers. Dug a test hole, sampled, closed pit. At 12' soil light gray with a H.C. odor.

Ground Water Encountered: No X Yes Depth

Final Pit:
Closure Sampling:
(if multiple samples, attach sample results and diagram of sample locations and depths)

Sample location Four walls and center of pit composite

Sample depth 12'

Sample Date 03/21/95 Sample time 14:35

Sample Results

Benzene(ppm) Not reported

Total BTEX(ppm) Not reported

Field headspace(ppm) 355

TPH 29300

Ground Water Sample: Yes No X (If yes, attach sample results)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Date 1/8/03
Signature Scott T. Pope

Printed Name SCOTT T. POPE
and Title Senior ENV. Scientist





Sec: 19 Unit: G
Land Type: Fee
Pit Closure Date: 03/21/95



PIT CLOSURE REQUEST

- Benzene, total BTEX, and TPH concentrations in the soil sample collected at the base of the Phase 2 soil boring at 22 ft bgs were non-detect, indicating that no significant downward constituent migration is occurring.
- Residual hydrocarbons, if any, in the soil will degrade by natural attenuation with minimal risk to the environment.

ATTACHMENTS


Field Pit Assessment Form
Revised Field Pit Assessment Form
Field Pit Remediation/Closure Form
Phase 2 Soil Boring Log
Laboratory Analytical Results

FIELD PIT SITE ASSESSMENT FORM

GENERAL	Meter: <u>72604</u> Location: <u>SAN JUAN 27-S #50 MU</u> Operator #: _____ Operator Name: <u>MERIDIAN P/L</u> District: <u>BLOOMFIELD</u> Coordinates: Letter: <u>6</u> Section <u>19</u> Township: <u>27</u> Range: <u>5</u> Or Latitude _____ Longitude _____ Pit Type: Dehydrator ☒ Location Drip: _____ Line Drip: _____ Other: _____ Site Assessment Date: <u>3-13-95</u> Area: <u>10</u> Run: <u>52</u>
SITE ASSESSMENT	NMOCD Zone: (From NMOCD Maps) Inside ☐ (1) Outside ☒ (2) Land Type: BLM ☐ (1) State ☐ (2) Fee ☒ (3) Indian _____ Depth to Groundwater Less Than 50 Feet (20 points) ☐ (1) 50 Ft to 99 Ft (10 points) ☒ (2) Greater Than 100 Ft (0 points) ☐ (3) Wellhead Protection Area : Is it less than 1000 ft from wells, springs, or other sources of fresh water extraction? , or ; Is it less than 200 ft from a private domestic water source? ☐ (1) YES (20 points) ☒ (2) NO (0 points) Horizontal Distance to Surface Water Body Less Than 200 Ft (20 points) ☐ (1) 200 Ft to 1000 Ft (10 points) ☒ (2) Greater Than 1000 Ft (0 points) ☐ (3) Name of Surface Water Body <u>EPHEMERAL DRAINAGE TO CEREZA CANYON</u> (Surface Water Body : Perennial Rivers, Major Wash, Streams, Creeks, Irrigation Canals, Ditches, Lakes, Ponds) Distance to Nearest Ephemeral Stream ☐ (1) < 100' (Navajo Pits Only) ☐ (2) > 100' TOTAL HAZARD RANKING SCORE: <u>20</u> POINTS
EMARKS	Remarks : <u>REDLINE SHOWS INSIDE BUT TOPO SHOWS LOCATION OUTSIDE</u> <u>V.I.Z. THREE PITS ON LOCATION. LOCATION DRIP PIT AND UNUSED DEHY</u> <u>PIT BELONG TO EPNG. WILL CLOSE BOTH OF THEM.</u>

ORIGINAL PIT LOCATION

REMARKS



PHOTOS - 1402

PHOTOS - 1402

[illegible]

Completed By:

Det Chapman

Signature

3.13.95

Date _____

REVISED FIELD PIT SITE ASSESSMENT FORM

GENERAL

Meter: 72604 Location: San Juan 27-5 #50 MV
 Operator #: _____ Operator Name: _____ P/L District: _____
 Coordinates: Letter: G Section 19 Township: 27 Range: 5
 Or Latitude _____ Longitude _____
 Pit Type: Dehydrator _____ Location Drip: _____ Line Drip: _____ Other: _____
 Site Assessment Date: 12/18/97 Area: _____ Run: _____

SITE ASSESSMENT

NMOCD Zone:

(From NMOCD
Maps)

Inside

Outside

Land Type:

BLM

State

Fee

Indian

☐ (1)

☐ (2)

☒ (3)

Depth to Groundwater

Less Than 50 Feet (20 points)

50 Ft to 99 Ft (10 points)

Greater Than 100 Ft (0 points)

☐ (1)

☒ (2)

☐ (3)

Wellhead Protection Area

Is it less than 1000 ft from wells, springs or other sources of fresh water extraction?, or; Is it less than 200 ft from a private domestic water source?

☐ (1) YES (20 points)

☒ (2) NO (0 points)

Horizontal Distance to Surface Water Body

Less Than 200 Ft (20 points)

200 Ft to 1000 Ft (10 points)

Greater Than 1000 Ft (0 points)

☐ (1)

☐ (2)

☒ (3)

Name of Surface Water Body _____

(Surface Water Body: Perennial Rivers, Streams, Creeks, Irrigation Canals, Ditches, Lakes, Ponds)

Distance to Nearest Ephemeral Stream

☐ (1) < 100' (Navajo Pits Only)

☐ (2) > 100'

TOTAL HAZARD RANKING SCORE: 10 POINTS

REMARKS

Remarks : Site has been re-assessed, due to initial assessment including washes as a Surface Water Body. Site is >1000' from the center of Cereza Canyon.



FIELD SERVICES LABORATORY

ANALYTICAL REPORT

PIT CLOSURE PROJECT - Soil Samples Outside the GWV Zone

SAMPLE IDENTIFICATION

	Field ID	Lab ID
SAMPLE NUMBER:	KP 461	946755
MTR CODE SITE NAME:	72604	N/A
SAMPLE DATE TIME (Hrs):	3-21-95	1435
SAMPLED BY:	N/A	
DATE OF TPH EXT. ANAL:	3/28/95	3/28/95
DATE OF BTEX EXT. ANAL:	N/A	N/A
TYPE DESCRIPTION:	V6	Brown sand & clay

REMARKS:

RESULTS

PARAMETER	RESULT	UNITS	QUALIFIERS			
			DF	Q	M(g)	V(ml)
TPH (418.1)	29300 29310	1000 3/28/95 MG/KG			0.32	28
HEADSPACE PID	355	PPM				
PERCENT SOLIDS	85.3	%				

-- TPH is by EPA Method 418.1 --

Narrative:

DF = Dilution Factor Used

Approved By:

JR

Date:

4/6/95

FIELD PIT REMEDIATION/CLOSURE FORM

GENERAL

Meter: 72604 Location: SAN JUAN 27-5 #50 MY
 Coordinates: Letter: 6 Section 19 Township: 27 Range: 5
 Or Latitude _____ Longitude _____
 Date Started : 3-21-95 Run: 10 52

FIELD OBSERVATIONS

Sample Number(s): KP 461
 Sample Depth: 12' Feet
 Final PID Reading 355 PID Reading Depth 12' Feet
 Yes No
 Groundwater Encountered ☐ ☒ Approximate Depth _____ Feet

CLOSURE

Remediation Method :
 Excavation ☐ Approx. Cubic Yards _____
 Onsite Bioremediation ☐
 Backfill Pit Without Excavation ☒
 Soil Disposition:
 Envirotech ☐ Tierra ☐
 Other Facility ☐ Name: _____
 Pit Closure Date: 3-21-95 Pit Closed By: B.EJ

REMARKS

Remarks : No Line Markers. dug A test hole sampled
closed Pit. At 12' soil light gray with a H.C odor.

Signature of Specialist: Kelly Padilla



Page _____ of _____

FM-08-0585 A (Rev. 05-94).

RECORD OF SUBSURFACE EXPLORATION

LIF SERVICES CORP.
J M Road
Bingham, New Mexico 87401
313 326-2262 FAX (505) 326-2388

Borehole # BH- 1
Well # NA
Page 1 of 1

Project Number 19643 Phase 1001.77
Project Name EPFS PITS >10
Project Location SAN JUAN 27-5#50 MV 72604

Elevation
Borehole Location LTR: 6 S: 19 T: 27 R: 5
ML Depth NA
Filled By K. PADILLA
Well Logged By H. BRADBURY
Date Started 11/5/98
Date Completed 11/5/98

Drilling Method 4 1/4 ID HSA
Air Monitoring Method PID

Depth (Feet)	Sample Number	Sample Interval	Sample Type & Recovery (inches)	Sample Description Classification System: USCS	USCS Symbol	Depth Lithology Change (feet)	Air Monitoring Units: PPM			Drilling Conditions & Blow Counts
							BZ	BH	S/HS	
0										BZ=Breathing Zone BH=Borehole S/HS=Sample/Headspace
5										
10				EXCAVATION sample collected AT 12'						
15	1	15-17	24	LT BR SAND, FINE SAND loose, dry			0	1	0	1258 hrs
20	2	20-22	24	LT BR SAND, FINE SAND loose, dry			0	0	0	1305 hrs
25				TOB 22'						
30										
35										
40										

Comments: HAB63 (20-22) SENT TO LAB FOR TPH BTEX GW NOT
ENCOUNTERED, BH GROUTED TO SURFACE

Geologist Signature Holly Bradbury



**FIELD SERVICES LABORATORY
ANALYTICAL REPORT
PIT CLOSURE PROJECT**

SAMPLE IDENTIFICATION

	Field ID	Lab ID
SAMPLE NUMBER:	HAB63	980790
MTR CODE SITE NAME:	72604	San Juan 27-5 #50 MV
SAMPLE DATE TIME (Hrs):	11/5/98	1305
PROJECT:	Phase II Drilling	
DATE OF TPH EXT. ANAL.:	11/10/98	11/10/98
DATE OF BTEX EXT. ANAL.:	11/9/98	11/9/98
TYPE DESCRIPTION:	VG	SOIL

Field Remarks: 20-22'

RESULTS

PARAMETER	RESULT	UNITS	QUALIFIERS			
			DF	Q	M(g)	V(ml)
BENZENE	<0.5	MG/KG				
TOLUENE	<0.5	MG/KG				
ETHYL BENZENE	<0.5	MG/KG				
TOTAL XYLENES	<1.5	MG/KG				
TOTAL BTEX	<3	MG/KG				
TPH (MOD.8015)	<20	MG/KG				
HEADSPACE PID	0	PPM				
PERCENT SOLIDS	95.9	%				

-- TPH is by EPA Method 8015 and BTEX is by EPA Method 8020 --

Surrogate Recovery was at 101.6 % for this sample All QA/QC was acceptable.
ative:

DF = Dilution Factor Used

Approved By: *[Signature]*

Date: 12/3/98

PLEASE FILL THIS FORM IN COMPLETELY.

[illegible]

SHADED AREAS ARE FOR LAB USE ONLY

PLEASE FILL THIS FORM IN COMPLETELY.

PROJECT MANAGER: John Lambdin
 COMPANY: E1 Paso Field Services
 ADDRESS: 770 West Navajo
 Farmington, NM 87401
 PHONE: (505) 599-2144
 FAX: (505) 599-2261
 BILL TO: Above
 COMPANY:
 ADDRESS:

SAMPLE ID	DATE	TIME	ANALYST	LAB ID	TESTS REQUESTED	TEST RESULTS
980789	11/5/98	1131	Soi	104	Petroleum Hydrocarbons (418.1) TRPH (MOD.8015) Diesel/Direct Inject (M8015) Gas/Purge & Trap 8021 (BTEX)/8015 (Gasoline) 8021 (BTEX) ☐ MTBE ☐ TMB ☐ PCE 8021 (TCL) 8021 (EDX) 8021 (HALO) 8021 (CUST) 504.1 EDB ☐ / DBCP ☐ 8260 (TCL) Volatile Organics 8260 (Full) Volatile Organics 8260 (CUST) Volatile Organics 8260 (Landfill) Volatile Organics Pesticides /PCB (608/8081) Herbicides (615/8151) Base/Neutral/Acid Compounds GC/MS (625/8270) Polynuclear Aromatics (610/8310) General Chemistry: Priority Pollutant Metals (13) Target Analyte List Metals (23) RCRA Metals (8) RCRA Metals by TCLP (Method 1311) Metals:	

PROJECT INFORMATION		PRIORITY/THOROUGHNESS REQUIRED FOR RUSH PROJECTS	
PROJ. NO.:	Phase II Drilling	(RUSH) ☐ 12hr ☐ 48hr ☐ 72hr ☐ 1 WEEK	(NORMAL) ☒
PROJ. NAME:	Phase II Drilling	CERTIFICATION REQUIRED: ☐ NM ☐ SDWA ☐ OTHER	
P.O. NO.:		METHANOL PRESERVATION ☐	
SHIPPED VIA:	FEDEX	COMMENTS: FIXED FEE ☐	
SAMPLE RECEIPT			
NO. CONTAINERS	1		
CUSTODY SEALS	Y/N/NA		
RECEIVED INTACT	YES		
LAB USE			

RECEIVED BY		RECEIVED BY (LAB)	
Signature:	Time: 1000	Signature:	Time: 1630
Printed Name: Markon Hoyer	Date: 11/9/98	Printed Name:	Date:
Company: EPFS		Company:	
Signature:	Time:	Signature:	Time:
Printed Name:	Date:	Printed Name:	Date:
Company:		Company:	

SHADED AREAS ARE FOR LAB USE ONLY

PLEASE FILL THIS FORM IN COMPLETELY.

PROJECT MANAGER: John Lambdin		COMPANY: El Paso Field Services	
ADDRESS: 770 West Navajo		PHONE: (505) 599-2144	
PHONE: (505) 599-2261		FAX:	
BILL TO: Above		COMPANY:	
ADDRESS:		ADDRESS:	
SAMPLE ID: 980790	DATE: 11/5/98	TIME: 1305	LAB ID: 1000
PETROLEUM HYDROCARBONS (418.1) TRPH			
☒ (MOD.8015) Diesel/Direct Inject			
☐ (M8015) Gas/Purge & Trap			
☐ 8021 (BTX)/8015 (Gasoline)			
☐ 8021 (BTX) ☐ MTBE ☐ TMB ☐ PCE			
☐ 8021 (TCL)			
☐ 8021 (EDX)			
☐ 8021 (HALO)			
☐ 8021 (CUST)			
☐ 504.1 EDB ☐ / DBCP ☐			
☐ 8260 (TCL) Volatile Organics			
☐ 8260 (Full) Volatile Organics			
☐ 8260 (CUST) Volatile Organics			
☐ 8260 (Landfill) Volatile Organics			
☐ Pesticides /PCB (608/8081)			
☐ Herbicides (615/8151)			
☐ Base/Neutral/Acid Compounds GC/MS (625/8270)			
☐ Polynuclear Aromatics (610/8310)			
☐ General Chemistry:			
☐ Priority Pollutant Metals (13)			
☐ Target Analyte List Metals (23)			
☐ RCRA Metals (8)			
☐ RCRA Metals by TCLP (Method 1311)			
☐ Metals:			
NUMBER OF CONTAINERS:			
PROJECT INFORMATION		PRIOR AUTHORIZATION IS REQUIRED FOR RUSH PROJECTS	
PROJ. NO.:	PROJ. NAME: Phase II Drilling	(RUSH) ☐ 24hr ☐ 48hr ☐ 72hr ☐ 1 WEEK	(NORMAL) ☒
P.O. NO.:		CERTIFICATION REQUIRED: ☐ NM ☐ SOWA ☐ OTHER	
SHIPPED VIA: FedEx		METHANOL PRESERVATION ☐	
SAMPLE RECEIPT		COMMENTS: FIXED FEE ☐	
NO. CONTAINERS: 1			
CUSTODY SEALS: 1			
RECEIVED INTACT: Yes			
LAB OFFICE:			
RELINQUISHED BY:		RELINQUISHED BY:	
Signature: [Signature]	Time: 1000	Signature:	Time:
Printed Name: Mark Hopper	Date: 11/9/98	Printed Name:	Date:
Company: EPFS		Company:	
RECEIVED BY:		RECEIVED BY:	
Signature: [Signature]	Time: 1030	Signature:	Time:
Printed Name: [Name]	Date: 11/10/98	Printed Name:	Date:
Company: American Environmental Network (NM), Inc.		Company:	

SHADED AREAS ARE FOR LAB USE ONLY.

PLEASE FILL THIS FORM IN COMPLETELY.

PROJECT MANAGER: John Lambdin		COMPANY: E1 Paso Field Services	
ADDRESS: 770 West Navajo		PHONE: Farmington, NM 87401	
FAX: (505) 599-2444		ADDRESS: (505) 599-2261	
BILL TO: Above		COMPANY:	
ADDRESS:		ADDRESS:	
SAMPLE ID: 980791		DATE: 11/5/98	
TIME: 1540		LAB ID: 501	
ANALYSIS REQUEST:		ANALYSIS REQUEST:	
☒ Petroleum Hydrocarbons (418.1) TRPH		☐ (MOD.8015) Diesel/Direct Inject	
☐ (M8015) Gas/Purge & Trap		☐ 8021 (BTX)/8015 (Gasoline)	
☐ 8021 (BTX) ☐ MTBE ☐ TMB ☐ PCE		☐ 8021 (TCL)	
☐ 8021 (EDX)		☐ 8021 (HALO)	
☐ 8021 (CUST)		☐ 504.1 EDB ☐ DBCP ☐	
☐ 8260 (TCL) Volatile Organics		☐ 8260 (Full) Volatile Organics	
☐ 8260 (CUST) Volatile Organics		☐ 8260 (Landfill) Volatile Organics	
☐ Pesticides /PCB (608/8081)		☐ Herbicides (615/8151)	
☐ Base/Neutral/Acid Compounds GC/MS (625/8270)		☐ Polynuclear Aromatics (610/8310)	
☐ General Chemistry:		☐ Priority Pollutant Metals (13)	
☐ Target Analyte List Metals (23)		☐ RCRA Metals (8)	
☐ RCRA Metals by TCLP (Method 1311)		☐ Metals:	
NUMBER OF CONTAINERS:		NUMBER OF CONTAINERS:	
PROJECT INFORMATION:		PRIOR AUTHORIZATION IS REQUIRED FOR RUSH PROJECTS:	
PROJ. NO.:	(RUSH) ☐ 124hr ☐ 48hr ☐ 72hr ☐ 1 WEEK	(NORMAL) ☒	
PROJ. NAME: Phase II Drilling	CERTIFICATION REQUIRED: ☐ NM ☐ SDWA ☐ OTHER		
P.O. NO.:	METHANOL PRESERVATION ☐		
SHIPPED VIA: Fed Ex	COMMENTS: FIXED FEE ☐		
SAMPLE RECEIPT:			
NO. CONTAINERS: 1			
CUSTODY SEALS: (N) N/A			
RECEIVED INTACT: YES			
PLUMBER:			
RECEIVED BY:		RECEIVED BY:	
Signature: [Signature]	Time: 1000	Signature: [Signature]	Time: 1030
Printed Name: Marlon Hopper	Date: 11/9/98	Printed Name: [Signature]	Date: 11/10/98
Company: EPPS		Company: American Environmental Network (NM), Inc.	
DISTRIBUTION:		DISTRIBUTION:	
AEN Inc.: American Environmental Network (NM), Inc. • 2709-D Pan American Freeway, N. • Albuquerque, New Mexico 87107 • (505) 344-3777 • Fax (505) 344-4413		DISTRIBUTION: AEN - AEN, Canary - Ohi	

PINNACLE
LABORATORIES

2709-D Pan American Freeway NE
Albuquerque, New Mexico 87107
Phone (505) 344-3777
Fax (505) 344-4413

GAS CHROMATOGRAPHY RESULTS

TEST : EPA 8015 MODIFIED (DIRECT INJECT)
CLIENT : EL PASO FIELD SERVICES
PROJECT # : (none)
PROJECT NAME : PHASE II DRILLING

PINNACLE I.D.: 811025

SAMPLE		MATRIX	DATE	DATE	DATE	DIL.
ID. #	CLIENT I.D.		SAMPLED	EXTRACTED	ANALYZED	FACTOR
04	980724 89	NON-AQ	11/5/98	11/10/98	11/10/98	1
05	980725 90	NON-AQ	11/5/98	11/10/98	11/10/98	1
06	980728 91	NON-AQ	11/5/98	11/10/98	11/10/98	1
PARAMETER		DET. LIMIT	UNITS	04	05	06
FUEL HYDROCARBONS, C6-C10		10	MG/KG	76	< 10	< 10
FUEL HYDROCARBONS, C10-C22		5.0	MG/KG	96	< 5.0	< 5.0
FUEL HYDROCARBONS, C22-C36		5.0	MG/KG	33	< 5.0	< 5.0
CALCULATED SUM:				205		

SURROGATE:
O-TERPHENYL (%)
SURROGATE LIMITS (66 - 151)

88 86 89

CHEMIST NOTES:
N/A

**PINNACLE
LABORATORIES**

2709-D Pan American Freeway NE
Albuquerque, New Mexico 87107
Phone (505) 344-3777
Fax (505) 344-4413

GAS CHROMATOGRAPHY RESULTS

TEST : EPA 8015 MODIFIED (DIRECT INJECT)
CLIENT : EL PASO FIELD SERVICES
PROJECT # : (none)
PROJECT NAME : PHASE II DRILLING

PINNACLE I.D.: 811025

SAMPLE		MATRIX	DATE	DATE	DATE	DIL.
ID. #	CLIENT I.D.		SAMPLED	EXTRACTED	ANALYZED	FACTOR
01	980771	NON-AQ	11/2/98	11/10/98	11/10/98	1
02	980772	NON-AQ	11/2/98	11/10/98	11/12/98	20
03	980773	NON-AQ	11/2/98	11/10/98	11/10/98	1
PARAMETER		DET. LIMIT	UNITS	01	02	03
FUEL HYDROCARBONS, C6-C10		10	MG/KG	13	8000	< 10
FUEL HYDROCARBONS, C10-C22		5.0	MG/KG	160	1300	< 5.0
FUEL HYDROCARBONS, C22-C36		5.0	MG/KG	120	320	< 5.0
CALCULATED SUM:				293	9620	

SURROGATE:
O-TERPHENYL (%)
SURROGATE LIMITS (66 - 151)

89 97 99

CHEMIST NOTES:
N/A