



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office 079181
Lease No. ---
Unit ---

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 4, 1957

Well No. 4-8 is located 330 ft. from N line and 330 ft. from E line of sec. 8
SW SW SW, Sec. 8 19N 5W NMPM
(¼ Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wildcat McKinley New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6600 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well to test Point Lookout sandstone at depth of 2200'. Drill 13 3/4" surface hole; set 1 to 3 joints of 8 5/8" surface pipe circulated to surface with cement. Drill 7 7/8" hole to 2200' or production at a lesser depth. Run 5 1/2" casing and test or plug and abandon, as case may be.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Caswell Silver
 Address 323 Simms Building
Albuquerque, New Mexico

By Caswell Silver
 Title Operator

APPROVED

10-10-10

10-10-10

