

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

## NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

FILE COPY

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input type="checkbox"/>
5. <del>State of New Mexico</del>
Santa Fe R. R. Lands.

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <b>DRY HOLE.</b>	7. Unit Agreement Name none.
2. Name of Operator <b>Ramsey Petroleum Company.</b>	8. Farm or Lease Name "Cactus Flower".
3. Address of Operator <b>P. O. Box 11446. Albuquerque, N. M. 87112.</b>	9. Well No. 1.
4. Location of Well UNIT LETTER <b>E</b> <b>1500'</b> FEET FROM THE <b>North</b> LINE AND <b>860'</b> FEET FROM THE <b>West</b> LINE, SECTION <b>20.</b> TOWNSHIP <b>17-N.</b> RANGE <b>7-W.</b> NMPM.	10. Field and Pool, or Wildcat <b>Wildcat.</b>
11. Elevation (Show whether DF, RT, GR, etc.) <b>6807' Ground.</b>	12. County <b>McKinley.</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

NOTE: Approval to plug was obtained by  
OTHER geologist Dave Thomas jr. at  
11:AM Dec. 4th from Oil Comm. Aztec, N. M.

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

Spud Date: Nov. 19, 1973. Reached T. D.: December 4, 1973. TD: 4,105 Ft.

Plugged by: Signal Oilfield Service Drilling Co., and Dowell Cementing Co.

Started setting Cement plugs: 5:00 Pm Completed: 7:45 PM. December 4, 1973.

## CEMENT PLUGS SET:

Surface - - - - - 5 sacks.  
150' - 200' - - - - - 14 Sx.  
700' - 800' - - - - - 28 Sx.  
1900' - 2050' - - - - - 42 Sx.  
2800' - 2900' - - - - - 28 Sx.  
3100' - 3200' - - - - - 28 Sx.  
4051' - 4101' - - - - - 14 Sx.

\* \* \* \* \*

Dry Hole Marker installed.

Pits are fenced, as soon as they dry out,  
all pits, location and road will be leveled.

(Total Dry Hole, no shows whatsoever).

Geology by: Gene D. Wilson.  
Albuquerque, N. M.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Arthur B. Ramsey TITLE Operator. DATE December 11, 1973.

APPROVED BY Ernest C. Thayer TITLE Reg. Sec. III DATE 12-4-73  
CONDITIONS OF APPROVAL, IF ANY:

