

UNITED STATES

DEPARTMENT OF THE INTERIOR

B. LEASE

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or plug back to a different horizon. Use Form 9-331-C for such proposals.

1. oil well ☒ gas well ☐ other ☐

2. NAME OF OPERATOR
Folk & Burge Oil Co., Inc.

3. ADDRESS OF OPERATOR
P.O. Box 179, Aztec, New Mexico 87410

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) 1870' FSL & 860' FWL (NW SW)

AT SURFACE: Same

AT TOP PROD. INTERVAL: Same

AT TOTAL DEPTH: Same

5. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) ☐

SUBSEQUENT REPORT OF:

RECEIVED


OCT 12 1982

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

U. S. GEOLOGICAL SURVEY
FARMINGTON, N. M.

6. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Spudded on August 28, 1982 with a 9" hole and drilled 88.7'. Set 88.7' of 7 5/8" casing and cemented to surface. Tested surface pipe to 500 pounds by pressuring with the mud pump. Then drilled 6 1/2" hole and tested the Mesaverdes. Reached T.D. of 2125' on September 8, 1982 and ran 4 1/2" casing. Cemented with 160 sxs.



Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED _____

TITLE _____

DATE _____

(This space for Federal or State office use)

APPROVED BY _____

TITLE _____

DATE _____

CONDITIONS OF APPROVAL, IF ANY:

COPIES FOR RECORD

OCT 15 1982

Nmocc

*See Instructions on Reverse Side

OPERATOR