
## MERRION OIL & GAS CORPORATION

Pot Mesa No. 4 Sec. 10, T20N, R6W McKinley Co., New Mexico

## SLOPE TESTS

<u>Depth</u>	Hole Deviation	
750	3/4	
1500	1/2	
2203	1	
3156	3/4	
3180	3/4	



State of New	Mexico	) ss	
County of San	Juan		SS

I, Steven S. Dunn , being first duly sworn, depose and state that the above and foregoing depth and hole deviation figures are true and correct to the best of my information and belief.

Subscribed and sworn before me this \_\_30th

day of December, 1985

My Commission Expires Just 16, 1989

