

MERRION OIL & GAS CORPORATION

Federal 21 No. 4
330' FSL and 2310' FWL
Sec. 21, T20N, R5W
McKinley County, New Mexico

SLOPE TESTS

<u>Depth</u>	<u>Hole Deviation</u>
217'	1/4° N85W
590'	1/2° N65E
838'	1/4°
1,334'	3/4° S31E
1,825'	3/4° S50E
2,321'	1° S45E
2,827'	3/4° S40E
3,331'	1/2° S15E
3,629'	1/2° S13E
4,172'	3/4° S07E
4,675'	1° N50W
4,931'	1-1/2° N82W
5,430'	1°
5,895'	1°

RECEIVED
JUN 29 1988
OIL CON. DIV.
DIST. 3

State of New Mexico)
County of San Juan) ss

I, Steven S. Dunn, being first duly sworn, depose and state that the above and foregoing depth and hole deviation figures are true and correct to the best of my information and belief.

Subscribed and sworn before me this 29th day of June.

Linda K. Horst
Notary Public