



STATE OF NEW MEXICO

ENERGY, MINERALS and NATURAL RESOURCES DIVISION
OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE



BRUCE KING
GOVERNOR

ANITA LOCKWOOD
CABINET SECRETARY

1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO 87410
(505) 334-6178

August 4, 1993

Mr. Bud Crane
Dugan Production Corp.
PO Box 420
Farmington, NM 87499

RE: Illegal Pits in Northwest New Mexico
Adobe #1, A-5-23N-07W (Tank Drain and Separator pits)

Dear Bud:

Field inspections conducted by Ernie Busch on July 22, 1993 revealed that the above mentioned pits have been netted as per requested. The pits are now in compliance and no longer require C-134 exceptions.

If you have any questions please feel free to call this office.

Yours truly,

Dianna K. Fairhurst

Dianna K. Fairhurst
Deputy Oil & Gas Inspector

xc: Don Ellsworth - BLM Farmington
C-134 Correspondence
Well File

RESUBMITTING
TO NMOC -
See No. 2 Below
Submit 4 Copies
to Appropriate
District Office

4 NMOC

1 File

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-134
Aug. 1, 1989

DISTRICT I
P.O. Box 1980, Hobbs, NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88211-0719

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

Permit No. _____
(For Division Use Only)

APPLICATION FOR EXCEPTION TO DIVISION ORDER R-8952 FOR PROTECTION OF MIGRATORY BIRDS Rule 8(b); Rule 105(b), Rule 312(h), Rule 313, or Rule 711(I)

Operator Name: DUGAN PRODUCTION CORP.

Operator Address: P.O. Box 420, Farmington, NM 87499

Lease or Facility Name Adobe #1 (pit #1 of 2) Location A-5-23N-7W

Size of pit or tank: approx. 12' x 12' (SEPARATOR) Ut. Ltr. Sec. Twp. Rge

Operator requests exception from the requirement to screen, net or cover the pit or tank at the above-described facility.

X The pit or tank is not hazardous to migratory waterfowl. Describe completely the reason pit is non-hazardous.
Pit is not large enough to attract migratory waterfowl, generally does not contain fluid, and generally does not contain hazardous material.

1) If any oil or hydrocarbons should reach this facility give method and time required for removal:
Oil or hydrocarbons requiring removal will be removed in the most efficient manner dependent upon variable circumstances. Most likely a vacuum truck will be used within 72 hours of the occurrence.

2) If any oil or hydrocarbons reach the above-described facility the operator is required to notify the appropriate District Office of the OCD with 24 hours.

Operator proposes the following alternate protective measures: _____

★ Pit Netted 12/10/92 - Bud Crane

CERTIFICATION BY OPERATOR: I hereby certify that the information given above is true and complete to the best of my knowledge and belief.

Signature Jim L. Jacobs

Title Geologist Date 10-2-89

Printed Name Jim L. Jacobs

Telephone No. 505-325-1821

FOR OIL CONSERVATION DIVISION USE

Date Facility Inspected 11/4/92

Inspected by Diana K. Jankhus

NOT APPROVED
SKIM OIL NO NET

7/23/93 ERNIE BUSCH INSPECTED -
1/3 FULL OF OIL - NOW NETTED

Approved by Diana K. Jankhus

Title _____

Date _____

AUG 4 1993

DEPUTY OIL & GAS INSPECTOR

★ RESUBMITTING TO 4 NMOC D
NMOC D - See No. 2 Below

1 File

Submit 4 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-134
Aug. 1, 1989

DISTRICT I
P.O. Box 1980, Hobbs, NM 88241-1980

OIL CONSERVATION DIVISION

DISTRICT II
P.O. Drawer DD, Artesia, NM 88211-0719

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

Permit No. _____
(For Division Use Only)

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

APPLICATION FOR EXCEPTION TO DIVISION ORDER R-8952 FOR PROTECTION OF MIGRATORY BIRDS Rule 8(b); Rule 105(b), Rule 312(h), Rule 313, or Rule 711(I)

Operator Name: DUGAN PRODUCTION CORP.

Operator Address: P.O. Box 420, Farmington, NM 87499

Lease or Facility Name Adobe #1 (pit #1 of 2 of 2) Location A-5-23N-7W

Size of pit or tank: approx. 10' x 10' (SMALL DRAIN PIT) Ut. Ltr. Sec. Twp. Rge

Operator requests exception from the requirement to screen, net or cover the pit or tank at the above-described facility.

☒ The pit or tank is not hazardous to migratory waterfowl. Describe completely the reason pit is non-hazardous.
Pit is not large enough to attract migratory waterfowl, generally does not contain fluid, and generally does not contain hazardous material.

1) If any oil or hydrocarbons should reach this facility give method and time required for removal:
Oil or hydrocarbons requiring removal will be removed in the most efficient manner dependent upon variable circumstances. Most likely a vacuum truck will be used within 72 hours of the occurrence.

2) If any oil or hydrocarbons reach the above-described facility the operator is required to notify the appropriate District Office of the OCD with 24 hours.

Operator proposes the following alternate protective measures:

★ Pit Netted 12/10/92 - Bud Crane

★ Fence Repaired 11/12/92

RECEIVED

OCT 16 1989

OIL CON. DIV

DIST. ?

CERTIFICATION BY OPERATOR: I hereby certify that the information given above is true and complete to the best of my knowledge and belief.

Signature Jim L. Jacobs Title Geologist Date 10-2-89

Printed Name Jim L. Jacobs Telephone No. 505-325-1821

FOR OIL CONSERVATION DIVISION USE

Date Facility Inspected 11/4/92

Inspected by Dianna K. Jankhusst

NOT APPROVED

H₂O SKIN OIL - NO NET

*REPAIR FENCE

7/23/93 ERNIE BUGCH INSPECTED -
1/2 FULL OF OIL - NOW NETTED, FENCE REPAIRED

Approved by

Title

Date

Dianna K. Jankhusst
AUG - 4 1993
DEPUTY OIL & GAS INSPECTOR