

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☒ gas well ☐ other ☐
2. NAME OF OPERATOR
DUGAN PRODUCTION CORP.
3. ADDRESS OF OPERATOR
P O Box 208, Farmington, NM 87401
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1650' FNL - 1650' FEL
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

5. LEASE NM 28736	
6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
7. UNIT AGREEMENT NAME	
8. FARM OR LEASE NAME Enniskillen	
9. WELL NO. 1	
10. FIELD OR WILDCAT NAME Lybrook Gallup	
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 9 T23N R6W	
12. COUNTY OR PARISH Rio Arriba	13. STATE NM
14. API NO.	
15. ELEVATIONS (SHOW DF, KDB, AND WD) 6743' GL	

REQUEST FOR APPROVAL TO:

- TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) ☐

SUBSEQUENT REPORT OF:

☐ RECEIVED
NOV 6 1981
U.S. GEOLOGICAL SURVEY
FARMINGTON, N.M.
☒ Status

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

See reverse for status of operations.



Subsurface Safety Valve: Mand. and Type

18. I hereby certify that the foregoing is true and correct

SIGNED Thomas A. Dugan TITLE Petroleum Engineer DATE 11-2-81

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:



dugan production corp.

DUGAN PRODUCTION CORP.
Enniskillen #1
1650' FNL - 1650' FEL
Sec 9 T23N R6W
Rio Arriba County, NM

MORNING REPORT

- 10-29-81 Moved in and rigged up Morrow drilling Co. rig.
Spudded 12 $\frac{1}{4}$ " hole at 5:00 p.m. 10-28-81. Drilled w/ air to
25'. S.D.O.N.
- 10-30-81 Depth 140' - Drilled to 140' w/ mist. S.D.O.N.
- 10-31-81 Drill on surface hole to 150'. Had problems keeping hole open.
S.D.O.N.
- 11-1-81 Attempt to drill surface hole with air. Hole caving badly.
W.O.O.
- 11-2-81 Hole caved - unable to clean out past 70'. Shut down. Wait on
Four Corners Rig #5.