
W. B. Martin & Associates

1300 Navajo • 2110 N. Sullivan Farmington, New Mexico 87401 (505) 327-1123



Hole Deviation Survey

Operator: William B. Martin and Associates

Well Name: #1 M & M

Well Location: 1650' FSL and 990'FEL

Section 15 Township 23N R4W Rio Arriba County, New Mexico

Gentlemen:

L and B Speedrill ran the following deviation surveys during the drilling of the subject well and obtained these results:

From	<u>To</u>	Deviation
-0-	120'	1/4° 1/2°
120'	720'	1/2 ⁰
720'	1220'	1/20
1220'	1660'	1/20
1660'	2060'	3/4 ⁰
20601	2400'	3/4 ⁰
2400'	2910'	3/4 ⁰

William B. Martin, Operator

Subscribed and Sworn to Me this 16th day of June, 1982

My Commission Expires

Notary Public