Form Approved. Budget Bureau No. 42-R1424

UNITED STATES

UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	Contract #362
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME Jicarilla Apache
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
1. oil gas other Dual Completion	9. WELL NO. #8 Martin-Florance
2. NAME OF OPERATOR	
W. B. Martin & Associates 3. ADDRESS OF OPERATOR	S. Lindrith Gallup-Dakota Ext.
2110 North Sullivan, Farmington NM 87401	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA NE NW 5
below.)	T23N R4W
AT SURFACE: 660' FNL and 1980' FWL AT TOP PROD. INTERVAL:	12. COUNTY OR PARISH 13. STATE
AT TOTAL DEPTH:	Rio Arriba N. M.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) GR. 69931
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	A special greater
TEST WATER SHUT-OFF	/ に リー
SHOOT OR ACIDIZE	erna.
REPAIR WELL PULL OR ALTER CASING	(NOTE: Report results of multiple completion or zone change on Form 9~330.)
MULTIPLE COMPLETE	
CHANGE ZONES U. S. GEOLOGICSL	SURVEY
ABANDON* Gompleted Operations G. S. GLOUNGTON	l/s . tAl:
(other) Compreded Operations	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly starting including estimated date of starting any proposed work. If well is a measured and true vertical depths for all markers and zones pertine)	directionally drilled, give subsurface locations and
Completed Operations: Total Depth 7070'	
Plugged Back 7031'	
	- FORING
	in Egelve
	-
Subsurface Safety Valve: Manu. and Type	Set @ Ft.
18. I hereby certify that the foregoing is true and correct	
SIGNED W. Marting TITLE Operator	DATE May 31, 1983
(This space for Federal or State office use)	
APPROVED BY TITLE DATE	
CONDITIONS OF APPROVAL, IF ANY:	
	GNODER ROTE BEST FEBRUARY

*See Instructions on Reverse Side