5. LEASE

#362

UNITED STATES DEPARTMENT OF THE INTERIOR CEOLOGICAL SURVEY

GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
GEOLOGIOAE CONTE	Jicarilla Apache
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
Do not use this form for proposals to drill or to deepen or plug back to a different eservoir. Use Form 9-331-C for such proposals.)	8. FARM OR LEASE NAME
1. oil gas other Dual Completion	9. WELL NO.
2. NAME OF OPERATOR	#9 Martin-Florance
W. B. Martin & Associates	10. FIELD OR WILDCAT NAME S. Lindrith Gallup Dakota Ext.
3. ADDRESS OF OPERATOR 2110 N. Sullivan, Farmington, NM 87401	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA NE SE 5 T23N R4W
below.) at surface: 1980' FSL & 660' FEL	12. COUNTY OR PARISH 13. STATE
AT SURFACE: 1980' FSL & 660' FEL AT TOP PROD. INTERVAL:	Rio Arriba NM
AT TOTAL DEPTH:	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	
REPORT, OR OTHER DATA	15. ELAVATIONS (SHOW DF, KDB, AND WD)
	Gr. 1063
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	and the state of t
TEST WATER SHUT-OFF U	
SHOOT OR ACIDIZE	
REPAIR WELL	(NOTE: Report results of multiple completion or zone
PULL OR ALTER CASING	at the charge on torm 3-333.
MULTIPLE COMPLETE	
ABANDON*	
(other) Cement Tops	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly statincluding estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones pertine Completed Operations: Cement Tops 5800', 5	nt to this work.)*
•	
	Car Mar 7 Store
	OIL CON. DIV
	Sat @ Ft
Subsurface Safety Valve: Manu. and Type	3et @1t.
18. I hereby certify that the foregoing is true and correct	
SIGNED W. P. Titate TITLE Operator	
(This space for Federal or State of	
APPROVED BY TITLE	DATE
CONDITIONS OF APPROVAL, IF ANY:	
	See
	ACCEPIEU FOR RESO

ACCEPIEU FOR RECORD

*See Instructions on Reverse Side

MAY 27 1983

FARMINGTON DISTRICT